





### General information

Make	AUDI
Model	A4 TDI S LINE
Colour	Silver
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	143 BHP
Max. torque	320 Nm at 2.100 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	51.4 mpg
CO2 emission	139 g/km
CO2 label	E







## Internet history

Entry 2		
Date		
Pictures		

2023-06-02

21

Listing price

View report



source: cargurus.co.uk

Entry 1		
Date		

Pictures

Listing price

2021-01-27 10

View report

source: autoonline.co.uk









## MOT history

MOT expiry date	2024-06-14	
MOT pass rate	86 %	
MOT passed	12	
Failed MOT tests	2	
Total advice items	36	
Total items failed	0	

MOT #14	2023-06-15 08:33
MOT test number	110784345012
Result	✓ Passed
Next expiry date	2024-06-14

MOT #13	2022-11-04 10:10
MOT test number	767169135731
Result	🗸 Passed
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorat grease (6.1.7 (g) (i))	ed has seepage of
Advice Front Outer nearside and offside sills heavily corroded holed out of prescribed	area borderline
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	





MOT #12		2022-10-29 10:46
MOT test	number	618848712065
Result		🗙 Failed
Advice	Front Outer nearside and offside sills heavily corroded holed out of prescribed	d area borderline
MAJOR	Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i	))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
<b>Minor</b> grease (6	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriora .1.7 (g) (i))	ated has seepage of
MAJOR	Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3	(i))
<b>MAJOR</b> reducing	Offside Front Suspension component mounting prescribed area excessively c structural strength inner wheel arch inner wing marked yellow (5.3.6 (a) (i))	orroded significantly
MOT #11		2021-11-05 13:25
MOT tost	numbor	807976206269

MOT test number	807976206269
Result	✓ Passed
<ul> <li>Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive front bush (5.3.4 (a) (i))</li> <li>Advice Offside Front Brake disc worn, but not excessively at upper limit (1.1.14 (a) (i))</li> <li>Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excession</li> </ul>	
rear bush (5.3.4 (a) (i))	
Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessiv rear bush (5.3.4 (a) (i))	e movement
Advice Nearside Front Brake disc worn, but not excessively at upper limit (1.1.14 (a) (i))	
<b>Advice</b> Nearside Front Upper Suspension arm pin or bush worn but not resulting in excess front bush (5.3.4 (a) (i))	ive movement





MOT #10		2021-10-23 14:18
MOT test	number	721468979366
Result		🗙 Failed
MAJOR	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of	dirt (2.1.3 (g) (ii))
Advice	Offside Front Brake disc worn, but not excessively at upper limit (1.1.14 (a) (i))	
MAJOR	Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3	3.4 (a) (i))
Advice front bush	Nearside Front Upper Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i))	essive movement
Advice front bush	Offside Front Upper Suspension arm pin or bush worn but not resulting in excess (5.3.4 (a) (i))	sive movement
Advice	Nearside Front Brake disc worn, but not excessively at upper limit (1.1.14 (a) (i)	)
MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5	.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Front Headlamp insecure (4.1.1 (c))	
Advice rear bush	Nearside Front Upper Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i))	essive movement
Advice rear bush	Offside Front Upper Suspension arm pin or bush worn but not resulting in excess (5.3.4 (a) (i))	sive movement
MOT #9		2020-11-02 16:48

MOT test	<b>number</b> 413069723663
Result	✓ Passed
<b>Advice</b> (5.3.4 (a)	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (i))
Advice	Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))





MOT #8	2020-02-04 17:56
MOT test number	874776781513
Result	✓ Passed
<b>Advice</b> Offside Front Lower Suspension arm pin or bush worn but not resrear arm bush (5.3.4 (a) (i))	sulting in excessive movement
<b>Advice</b> Nearside Front Lower Suspension arm pin or bush worn but not refront arm bush (5.3.4 (a) (i))	esulting in excessive movement
Advice Corrosion undrneath	
<b>Advice</b> Offside Front Lower Suspension arm pin or bush worn but not restrict front arm bush (5.3.4 (a) (i))	sulting in excessive movement
MOT #7	2018-01-30 12:03
MOT #7	978862199869
Result	✓ Passed
	•
MOT #6	2017-01-28 17:19
MOT test number	331487159827
Result	✓ Passed
MOT #5	2016-02-23 11:18
MOT test number	269292533458
Result	✓ Passed
MOT #4	2015-02-18 17:41
MOT test number	165429645400
Result	✓ Passed
Advice Tyre worn close to the legal limit (4.1.E.1)	
MOT #3	2014-02-14 13:30

MOT #3	2014-02-14 13:30
MOT test number	535475544020
Result	✓ Passed



<b>SP58</b>	LUY
report date:	2024-03-29

MOT #2	2013-01-31 09:02
MOT test number	798131733031
Result	✓ Passed
MOT #1	2012-02-08 12:01
MOT test number	345739632011
Result	✓ Passed
Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)	



Tax & MOT check

Taxed	✓ MOT Expires: 14 June 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	14 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	AF I
Category	ante.
Туре	

#### Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

*******	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-01
Last registration	2023-06-15
Complete history	See info



Registration #1	2008-09-01	10 mi
Registration #2	2012-02-08	60.008 mi
Registration #3	2013-01-31	68.730 mi
Registration #4	2014-02-14	87.209 mi
Registration #5	2015-02-18	103.258 mi
Registration #6	2016-02-23	107.435 mi
Registration #7	2017-01-28	111.146 mi
Registration #8	2018-01-30	115.237 mi
Registration #9	2020-02-04	118.365 mi
Registration #10		11.117 est
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1460 kg
Max. allowed weight	2010 kg
Additional information	
Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	CAG 131084