




report date: 2023-11-21

General information

Make	FIAT
Model	500 TWINAIR S
Colour	Blue
Year of manufacture	2017
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	90 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-01
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-09
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	3

MOT #6 2023-06-08 09:23

MOT test number 585580831391

Result ✔ Passed

Next expiry date 2024-06-09

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Play in steering rack inner joint(s)

Advice OSF, OSR and NSR tyres slightly perished.

Advice Nearside Front top strut mount has slight play

MOT #5 2023-06-08 09:01

MOT test number 167398300317

Result ✘ Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice OSF, OSR and NSR tyres slightly perished.

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front top strut mount has slight play

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Play in steering rack inner joint(s)



MOT #4 2022-06-09 08:06

MOT test number 672761773521

Result ✓ Passed

MOT #3 2021-06-07 09:57

MOT test number 182958906772

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-06-10 15:17

MOT test number 545920572029

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge. (5.2.3 (e))

Advice Nearside Front Road wheel slightly distorted inside rim. (5.2.2 (c) (i))

Minor Windscreen damaged but not adversely affecting driver's view Chip on nearside. (3.2 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened lipped both sides (1.1.14 (a) (ii))

MOT #1 2020-06-08 05:43

MOT test number 570794477255

Result ✓ Passed

Advice COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
9 June 2024

Tax status	Valid until 1 July
Days left	212
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
First licence fee (12 months)	£ 115,00,-
Standard rate (12 months)	£ 155,00,-
Standard rate (6 months)	£ 85,25,-
Premium rate (12 months)	£ 490,00,-
Premium rate (6 months)	£ 269,50,-




Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

Download >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

Download >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

Download >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	UK
Plate since	2019-09-29
Current registration	UK
Plate since	2019-09-29

Download >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

Download >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-06-16
Last registration	2023-06-08
Complete history	See info



Registration #1	2017-06-16	11 mi
Registration #2	2020-06-10	16.485 mi
Registration #3	2021-06-07	21.453 mi
Registration #4	2022-06-08	25.277 mi
Registration #5	2022-06-08	25.277 mi
Registration #6	2022-06-08	25.277 mi
Registration #7	2022-06-08	25.277 mi

Download >



Premium report

Get the FIAT premium report and get full access to more information.

- ✓ Finance check
- ✓ Mileage registrations (7)
- ✓ Damage check
- ✓ Stolen check
- ✓ Car features list
- ✓ Owners history + plate changes

Download >

Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

Download >



Safety ratings

NCAP rating	★★★★☆
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	0416682