



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Blue
Year of manufacture	2007
Top speed	129 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-04
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-10-13
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	46
Total items failed	27

MOT #18 2021-10-14 12:03

MOT test number 183257556408

Result ✓ Passed

Next expiry date 2022-10-13

- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17 2021-10-12 10:11

MOT test number 361615165800

Result ✗ Failed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Oil leaking excessively from transmission (8.4.1 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #16**

2020-10-14 08:05

MOT test number

209293201378

Result

✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2020-10-13 11:36

MOT test number

850734282722

Result

✗ Failed

Fail

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail

Offside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

Fail

Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

Nearside Front Oil leak, but not excessive driveshaft oil seal (8.4.1 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2019-10-10 12:23

MOT test number

496004474989

Result

✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Play in steering rack inner joint(s)

Advice

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #13**

2019-10-10 10:20

MOT test number

671430999978

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #12

2018-08-22 08:24

MOT test number

129411973445

Result**✓ Passed**

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2018-08-16 13:51

MOT test number

987595390540

Result**✗ Failed**

- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction object on mirror (3.1 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Parking brake performance just met
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Rear Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Seat belt damaged (7.1.2 (b) (i))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Reverse lamps not working

MOT #10

2017-08-20 12:28

MOT test number

550440281058

Result**✓ Passed**

- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #9

2016-08-26 11:56

MOT test number

140005570101

Result**✓ Passed**



MOT #8	2015-07-03 13:07
MOT test number	286004785491
Result	✓ Passed

MOT #7	2015-07-01 15:24
MOT test number	957692785172
Result	✗ Failed

- Fail** Nearside Front front brake excessively fluctuating (3.7.B.3)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Corrosion rear brake discs
- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front front brake excessively fluctuating (3.7.B.3)
- Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Notice** Excessive corrosion front brake discs (inner faces)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Headlamp aim too low (1.8)

MOT #6	2014-07-18 12:45
MOT test number	647459394157
Result	✓ Passed

**MOT #5** 2013-05-30 13:29**MOT test number** 596690053128**Result** ✓ Passed**Notice** REAR DISCS ARE HEAVILY PITTED**MOT #4** 2012-06-08 13:39**MOT test number** 829660562161**Result** ✓ Passed**MOT #3** 2011-05-24 12:22**MOT test number** 477764241172**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/r brake binding**MOT #2** 2011-05-24 11:07**MOT test number** 156034841165**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s/r brake binding**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-05-10 10:36**MOT test number** 833920030161**Result** ✓ Passed**Notice** Nail in nearside front tyre



Tax & MOT check

✕
Untaxed

Tax expired:
12 October 2022

✕
MOT

Expired:
13 October 2022

Tax status	Expired at 12 October 2022
Days left	565 days too late
MOT expiry date	13 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KV07EEY
Plate since	2019-03-28
Current registration	KV07EEY
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-10
Last registration	2021-10-14
Complete history	See info



Registration #1	2007-05-10	26 mi
Registration #2	2010-05-10	16.770 mi
Registration #3	2011-05-24	25.054 mi
Registration #4	2011-05-24	25.054 mi
Registration #5	2012-06-08	38.335 mi
Registration #6	2013-05-30	46.896 mi
Registration #7	2014-07-18	63.223 mi
Registration #8	2015-07-01	78.313 mi
Registration #9	2015-07-03	78.353 mi
Registration #10	2016-08-26	86.531 mi
Registration #11	2016-08-26	86.531 mi
Registration #12	2016-08-26	86.531 mi
Registration #13	2016-08-26	86.531 mi
Registration #14	2016-08-26	86.531 mi
Registration #15	2016-08-26	86.531 mi
Registration #16	2016-08-26	86.531 mi
Registration #17	2016-08-26	86.531 mi
Registration #18	2016-08-26	86.531 mi
Registration #19	2016-08-26	86.531 mi
Registration #20	2016-08-26	86.531 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1543 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH5C1581335