





report date: 2024-03-29

#### General information

| Make                | FIAT           |
|---------------------|----------------|
| Model               | PUNTO ACTIVE   |
| Colour              | Blue           |
| Year of manufacture | 2007           |
| Top speed           | 96 mph         |
| 0 - 60 mph          | 14.5 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 64 BHP              |
|-------------------------|---------------------|
| Max. torque             | 102 Nm at 3.000 rpm |
| Engine capacity         | 1.242 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 35.8 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 46.3 mpg            |
| CO2 emission            | 139 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/14



NU07FFD report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-22

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



NU07FFD report date: 2024-03-29

MOT history

| MOT expiry date    | 2024-10-22 |
|--------------------|------------|
| MOT pass rate      | 71 %       |
| MOT passed         | 12         |
| Failed MOT tests   | 5          |
| Total advice items | 37         |
| Total items failed | 10         |

| MOT #17  |  | 2023-10-23 11:53 |
|--|--|------------------|
| MOT test   | number   | 803948611125     |
| Result   |  | ✓ Passed         |
| Next expiry date 2024-1  |  | 2024-10-22       |
| Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) |  |                  |
| Advice   | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) | ))               |

| MOT #16  |   | 2022-06-09 10:23 |
|----------|---|------------------|
| MOT test | number  | 686336227999     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) |                  |
| Advice   | Offside Front Coil spring corroded (5.3.1 (b) (i))                          |                  |
| Advice   | Exhaust has a minor leak of exhaust gases (6.1.2 (a))                       |                  |
| Advice   | Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))     |                  |
| Advice   | Rear Coil spring corroded both sides (5.3.1 (b) (i))                        |                  |
| Advice   | Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))    |                  |

| MOT #15         | 2021-06-18 13:44 |
|-----------------|------------------|
| MOT test number | 681615908251     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #14

MOT test number

Result

Rear Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #13
 2020-08-17 14:34

 MOT test number
 828736688251

 Result
 ✓ Passed

**MOT #12** 2019-03-04 10:20 **MOT** test number 922467140971 Result ✓ Passed **Minor** Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i)) **Advice** Some dashboard lights glow dimly Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside rear upper sidelight not working **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2018-03-07 17:10

MOT test number 317883859891

Result ✓ Passed

MOT #10

MOT test number

Result

Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Notice Play in steering rack inner joint(s)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front brake fluctuating, but not excessively (3.7.B.3)

2015-07-23 09:26 **MOT #8 MOT** test number 545244505293 Result × Failed Fail Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d) Advice Front brake fluctuating, but not excessively (3.7.B.3) Fail Exhaust has a major leak of exhaust gases (7.1.2) Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Play in steering rack inner joint(s)

| MOT #7   |  | 2014-08-04 16:35 |
|----------|--|------------------|
| MOT test | number   | 955276514271     |
| Result   |  | ✓ Passed         |
| Notice   | Oil leak   |                  |
| Advice   | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |                  |
| Notice   | Exhaust deteriorated   |                  |
| Notice   | Both rear tyre treads & side walls deteriorated                              |                  |
| Advice   | Nearside Front Tyre worn close to the legal limit (4.1.E.1)                  |                  |

CarCheck.co.uk page 5/14



report date: 2024-03-29

2014-07-29 09:19 **MOT #6** 757520514224 **MOT** test number Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Exhaust deteriorated Notice Oil leak Fail Nearside Front coil spring broken (2.4.C.1a) Fail Exhaust system not adequately supported (7.1.1) **Notice** Both rear tyre treads deteriorated

MOT #5

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Exhaust deteriorated

MOT #4

MOT test number

Result

Advice

Tie bar/rod has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #2 2011-07-27 16:04 **MOT** test number 196398101295 Result × Failed **Advice** Exhaust has part of the system slightly deteriorated (7.1.1a) Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

| MOT #1          | 2010-04-30 09:45 |
|-----------------|------------------|
| MOT test number | 982370920123     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 7/14



NU07FFD report date: 2024-03-29

Tax & MOT check



| Tax status       | Valid until 1 April |
|------------------|---------------------|
| Days left        | 337                 |
| MOT expiry date  | 22 October 2024     |
| Full MOT history | See MOT history     |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



NU07FFD report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

# Owner history

| For how long did the current and previous owner(s) have this FIAT? How many owners did to Check it in the premium report and see all owner registrations. Download the full report here  |           | e? |
|--|-----------|----|
|  |           |    |
|  |           |    |
|  |           |    |
|  |           |    |
| THE PARTY OF THE P |           |    |
|  |           |    |
| ***************************************  |           |    |
|  | More info | >  |
| Plate changes  |           |    |
| See in this check if this FIAT had different number plates.  |           |    |
| Number of plates   |           |    |
| Current registration   | OK SIE    |    |
| Plate since  |           |    |
| Current registration   | NK SIE    |    |
| Plate since  |           |    |
|  | More info | >  |
|  |           |    |

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 18         |
| First mileage registration | 2007-03-30 |
| Last registration          | 2023-10-23 |
| Complete history           | See info   |



| Registration #1  | 2007-03-30 | 21 mi     |
|------------------|------------|-----------|
| Registration #2  | 2010-04-30 | 14.442 mi |
| Registration #3  | 2011-07-27 | 19.073 mi |
| Registration #4  | 2012-07-25 | 24.405 mi |
| Registration #5  | 2013-07-31 | 28.767 mi |
| Registration #6  | 2014-07-29 | 34.178 mi |
| Registration #7  | 2014-08-04 | 34.267 mi |
| Registration #8  | 2015-07-23 | 43.050 mi |
| Registration #9  | 2015-08-03 | 43.291 mi |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 11.777 au |

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1687 mm |
|---------------------|---------|
| Height              | 1490 mm |
| Length              | 4030 mm |
| Wheel base          | 2510 mm |
| Kerb weight         | 1030 kg |
| Max. allowed weight | 1590 kg |

# Additional information

| Fuel tank capacity                | 45 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 14/:           |

Number of axles 2
Engine number 4018117