





General information

Make	ΤΟΥΟΤΑ
Model	AURIS VVT-I EXCEL
Colour	Blue
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	305 Nm at 4.400 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	72.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	72.4 mpg
CO2 emission	91 g/km
CO2 label	А





Internet history		
Entry 1		
Date	2021-09-11	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #5		2023-09-19 15:01
MOT test	number	866683096873
Result		✓ Passed
Next exp	iry date	2024-09-29
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.	3.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside mirror side repeater lens damaged	
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakene	ed (5.3.3 (b) (i))
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.	3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened	(5.3.3 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriora	ated outer (5.3.4 (b) (i))





OT #4 2023-09-19 15:0
OT test number 18153366764
esult X Faile
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated outer (5.3.4 (b) (i))
Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice Offside mirror side repeater lens damaged
Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
Advice Items removed from driver's view prior to test
Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #3	2022-09-15 14:01
MOT test number	739700585693
Result	✓ Passed
Advice Nearside Rear Nail in tyre	
MOT #2	2021-09-30 16:32
MOT test number	960489516699
Result	✓ Passed
MOT #1	2021-03-01 14:21
MOT test number	655840031321
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 29 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	E
First licence fee (12 months)	£ 155,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Current registration Plate since	ж uk





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-02-27
Last registration	2023-09-19
Complete history	See info



Registration #1	2018-02-27	11 mi
Registration #2	2021-03-01	16.280 mi
Registration #3		11.777 mi
Registration #4	2021-09-30	18.193 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.227 mi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1760 mm
Height	1475 mm
Length	4330 mm
Wheel base	2600 mm
Kerb weight	1425 kg
Max. allowed weight	1840 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	2ZRV784043