



HD08HRC

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 SPORT LR P/V
Colour	Red
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-05-11
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	55
Total items failed	25

MOT #21	2023-05-12 11:48
---------	------------------

MOT test number	742239706936
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-11
------------------	------------

- Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Outer Suspension component mounting prescribed area damaged but not considered excessive O/S and N/S (5.3.6 (a) (i))
- Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Inner Suspension component mounting prescribed area damaged but not considered excessive O/S and N/S (5.3.6 (a) (i))
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**MOT #20**

2023-05-12 11:48

MOT test number

564836424961

Result

✗ Failed

Advice

Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice

Outer Suspension component mounting prescribed area damaged but not considered excessive O/S and N/S (5.3.6 (a) (i))

Advice

Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice

Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice

Inner Suspension component mounting prescribed area damaged but not considered excessive O/S and N/S (5.3.6 (a) (i))

Advice

Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Pass with rectification

Nearside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

MOT #19

2022-05-09 13:55

MOT test number

730854730885

Result

✓ Passed

Advice

Nearside Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Advice

Nearside Suspension component mounting prescribed area is corroded but not considered excessive door step (5.3.6 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Advice

Offside Suspension component mounting prescribed area is corroded but not considered excessive door step (5.3.6 (a) (i))

**MOT #18**

2022-05-09 13:55

MOT test number

829115754121

Result**✗ Failed**

Advice Nearside Suspension component mounting prescribed area is corroded but not considered excessive door step (5.3.6 (a) (i))

Pass with rectification Nearside Driver's view of an obligatory external mirror significantly affected by an obstruction (3.1 (a) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Advice Offside Suspension component mounting prescribed area is corroded but not considered excessive door step (5.3.6 (a) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #17

2021-02-23 11:27

MOT test number

685167903825

Result**✓ Passed**

Advice Offside Front headlight aim poor condition

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Lower Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #16** 2019-09-20 13:31**MOT test number** 521703651077**Result** ✓ Passed**MOT #15** 2018-09-21 07:04**MOT test number** 499352158213**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-09-20 09:57**MOT test number** 510087565195**Result** ✗ Failed**MAJOR** Brake lining(s) wear indicator illuminated (1.1.13 (a) (i))**MAJOR** Nearside Brake cable has restricted free movement (1.1.15 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #13** 2017-09-20 12:56**MOT test number** 420707981154**Result** ✓ Passed**Advice** Slight smoke from exhaust

**MOT #12**

2017-09-20 08:25

MOT test number

245363449967

Result**✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** N/s/r tyre splitting on sidewall**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Slight smoke from exhaust**MOT #11**

2016-09-19 17:25

MOT test number

368494000880

Result**✓ Passed****Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower arm rear bush (2.4.G.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear wheel bearing has slight play (2.6.2)

**MOT #10**

2016-09-16 12:52

MOT test number

158288163765

Result**✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower arm rear bush (2.4.G.2)
- Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Anti-roll bar has excessive play in a pin/bush d bush (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Suspension arm insecure ball join nut loose (2.4.G.1)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear wheel bearing has slight play (2.6.2)
- Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush d bush (2.4.G.2)

MOT #9

2015-08-26 00:00

MOT test number

642037377225

Result**✓ Passed****MOT #8**

2014-05-02 10:18

MOT test number

127252324141

Result**✓ Passed**

**MOT #7** 2014-05-02 10:18**MOT test number** 666482024123**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-04-30 11:07**MOT test number** 789260623186**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2013-04-30 09:53**MOT test number** 897850223156**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2012-07-18 16:09**MOT test number** 537780402266**Result** ✓ Passed**MOT #3** 2012-07-18 09:41**MOT test number** 357950202447**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Headlamp aim too low (1.8)



MOT #2	2011-07-19 12:48
MOT test number	438490601249
Result	✓ Passed

MOT #1	2011-07-19 12:43
MOT test number	317450601230
Result	✗ Failed
<div>Fail</div> Stop lamp not working (1.2.1b)	



Tax & MOT check

✖
Untaxed

Tax expired:
1 November 2023

✓
MOT

Expires:
11 May 2024

Tax status	Expired at 1 November 2023
Days left	179 days too late
MOT expiry date	11 May 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-29
Last registration	2023-05-12
Complete history	See info



Registration #1	2008-07-29	29 mi
Registration #2	2011-07-19	41.935 mi
Registration #3	2011-07-19	41.935 mi
Registration #4	2012-07-18	54.773 mi
Registration #5	2012-07-18	54.773 mi
Registration #6	2013-04-30	61.480 mi
Registration #7	2013-04-30	61.480 mi
Registration #8	2014-05-02	73.026 mi
Registration #9	2015-08-26	84.611 mi
Registration #10	2016-09-16	93.381 mi
Registration #11	2016-09-19	93.468 mi
Registration #12	2019-05-29	95.557 mi
Registration #13	2019-05-29	95.557 mi
Registration #14	2019-05-29	95.557 mi
Registration #15	2019-05-29	95.557 mi
Registration #16	2019-05-29	95.557 mi
Registration #17	2019-05-29	95.557 mi
Registration #18	2019-05-29	95.557 mi
Registration #19	2019-05-29	95.557 mi
Registration #20	2019-05-29	95.557 mi
Registration #21	2019-05-29	95.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1974 mm
Height	2067 mm
Length	4863 mm
Wheel base	2933 mm
Kerb weight	1710 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	8Y32525