



report date: 2024-03-29

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Blue
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-11-24
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-27
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	7
Total items failed	5

MOT #13	2024-02-28 17:30
MOT test number	842462191874
Result	✓ Passed
Next expiry date	2025-02-27

MOT #12	2023-07-13 10:04
MOT test number	539764353395
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin osf and nsf (1.1.13 (a) (ii))

MOT #11	2023-07-13 10:04
MOT test number	565410248133
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin osf and nsf (1.1.13 (a) (ii))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #10	2022-07-20 09:49
MOT test number	103129797834
Result	✓ Passed

**MOT #9** 2021-07-22 11:56**MOT test number** 220153140529**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2021-07-22 08:02**MOT test number** 525694407558**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2020-07-02 09:26**MOT test number** 183867156560**Result** ✓ Passed**MOT #6** 2020-07-02 09:26**MOT test number** 769860476957**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2019-07-11 12:22**MOT test number** 734704041594**Result** ✓ Passed



<b>MOT #4</b>	2018-07-26 08:30
---------------	------------------

<b>MOT test number</b>	995856389301
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2017-07-26 14:21
---------------	------------------

<b>MOT test number</b>	130056782077
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2017-07-26 09:06
---------------	------------------

<b>MOT test number</b>	259242571191
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

**Pass with rectification** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

<b>MOT #1</b>	2016-08-22 11:22
---------------	------------------

<b>MOT test number</b>	318668908908
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
27 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	27 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>LX63DXM</b>
Plate since	2019-03-29
Current registration	<b>LX63DXM</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-03
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2013-09-03	16 mi
Registration #2	2016-08-22	20.619 mi
Registration #3	2017-07-26	29.322 mi
Registration #4	2017-07-26	29.322 mi
Registration #5	2018-07-26	37.683 mi
Registration #6	2019-07-11	42.916 mi
Registration #7	2020-07-02	48.532 mi
Registration #8	2020-07-02	48.532 mi
Registration #9	2020-07-02	48.532 mi
Registration #10	2020-07-02	48.532 mi
Registration #11	2020-07-02	48.532 mi
Registration #12	2020-07-02	48.532 mi
Registration #13	2020-07-02	48.532 mi
Registration #14	2020-07-02	48.532 mi
Registration #15	2020-07-02	48.532 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

Engine number	CT29076
---------------	---------