





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|----------------|
| Model | KUGA LX TDCI |
| Colour | Silver |
| Year of manufacture | 2008 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 143 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 44.1 mpg |
| CO2 emission | 169 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1


Date 2021-03-05

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-05-31 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 26 |
| Total items failed | 11 |

| MOT #18 | 2023-05-25 08:58 |
|---|------------------|
| MOT test number | 975326145945 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-31 |
| Advice Sub-frame corroded but not seriously weakened Rear subframe and associated suspension components (5.3.3 (b) (i)) | |

| MOT #17 | 2022-05-23 10:39 |
|---|-----------------------|
| MOT test number | 694015068632 |
| Result | ✓ Passed |
| Advice Sub-frame corroded but not seriously weakened Rear subframe and components (5.3.3 (b) (i)) | associated suspension |

| MOT #16 | 2022-05-23 10:39 |
|---|--|
| MOT test number | 746037427192 |
| Result | ★ Failed |
| Pass with rectification | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Advice Sub-frame corroded but not seriously weakened Rear subframe and associated suspension components (5.3.3 (b) (i)) | |

| MOT #15 | 2021-05-14 14:17 |
|-----------------|------------------|
| MOT test number | 236545481202 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/14



report date: 2024-03-28

| MOT #14 | 2021-05-13 14:26 |
|--|------------------|
| MOT test number | 291878141069 |
| Result | X Failed |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |

| MOT #13 | 2020-06-01 11:45 |
|--|------------------|
| MOT test number | 749174653967 |
| Result | ✓ Passed |
| | |
| MOT #12 | 2019-06-06 15:14 |
| MOT test number | 592014752043 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2019-06-05 17:29 |
| MOT test number | 202047845523 |
| Result | ★ Failed |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #10 | 2018-05-25 09:31 |
|------------------------------------|------------------|
| MOT test number | 114204389592 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2017-03-21 09:47 |
| MOT test number | 125510745666 |
| Result | ✓ Passed |
| Advice Oil leak from steering rack | |

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number

601940949268

Result

Advice Oil leak from steering rack

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #7

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

Result

Notice

Under-trays fitted obscuring some underside components

2014-05-02 15:38

808462624198

✔ Passed

MOT test number

Result


Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/14



report date: 2024-03-28




| MOT #3 | | 2012-10-09 15:05 |
|----------|--|------------------|
| MOT test | number | 965483482212 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |
| Notice | Under-trays fitted obscuring some underside components | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Air bag warning light on dash | |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |

CarCheck.co.uk page 6/14



report date: 2024-03-28



| MOT #1 | 2011-10-07 11:21 |
|--|------------------|
| MOT test number | 196290481211 |
| Result | ✓ Passed |
| Notice Front tyre wearing slightly on inner edge | |

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 186 |
| MOT expiry date | 31 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| W 11 1 1 | 40 |
|---|------------|
| Vehicle class | 49 |
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | |
|--|--|
| | |
| THE STATE OF THE S | |
| | |
| | |
| ********* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| | |
| Current registration | UK NEW |
| Plate since | |
| Current registration | NIV. |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 19 |
| First mileage registration | 2008-10-08 |
| Last registration | 2023-05-25 |
| Complete history | See info |



| Registration #1 | 2008-10-08 | 6 mi |
|------------------|------------|-----------|
| Registration #2 | 2011-10-07 | 20.118 mi |
| Registration #3 | 2012-10-09 | 29.183 mi |
| Registration #4 | 2013-10-08 | 36.351 mi |
| Registration #5 | 2013-10-11 | 36.458 mi |
| Registration #6 | 2014-05-02 | 38.643 mi |
| Registration #7 | 2015-04-17 | 41.350 mi |
| Registration #8 | 2017-03-20 | 54.598 mi |
| Registration #9 | 2017-03-21 | 54.598 mi |
| Registration #10 | 2018-05-25 | 68.176 mi |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 91.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 0.77 44 |
| Registration #19 | | |

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1884 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1736 kg |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 70 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 14/1 |

Number of axles2Engine number8R41969