




report date: 2024-03-28

General information

Make	NISSAN
Model	CABSTAR DCI 34.12 DROPSIDE
Colour	White
Year of manufacture	2014
Top speed	82 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	250 Nm at 1.600 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	257 g/km
CO2 label	M





Internet history

Entry 1

Date 2021-07-23

Pictures 11

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-20
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	44
Total items failed	26

MOT #13	2024-01-18 15:08
MOT test number	224760790315
Result	✓ Passed
Next expiry date	2025-01-20
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #12	2023-01-10 16:30
MOT test number	829168175645
Result	✓ Passed
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #11

2021-12-23 11:06

MOT test number

267684776203

Result

✓ Passed

- Advice

Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2021-12-22 13:01

MOT test number

678174747445

Result**✗ Failed**

- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Nearside Front Headlamp light intensity severely reduced dip beam dull (4.1.4 (a))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #9

2021-01-21 15:50

MOT test number

709751077474

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2021-01-15 16:26**MOT test number** 495584919963**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Registration plate inscription illegible (0.1 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Service brake lagging in operation (1.2.1 (d))**Fail** Nearside Headlamp aim not tested (4.1.2 (b))**Fail** Offside Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Horn not working (7.7 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2019-07-17 11:06**MOT test number** 569500465837**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2019-07-17 10:46

MOT test number

238866129638

Result**✗ Failed****Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Advice** Nearside Front Nail in tyre**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5**

2019-06-20 10:50

MOT test number

349907877466

Result**✗ Failed****Advice** Nearside Front Nail in tyre**Advice** Nearside Rear Outer Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Non obligatory mirror damaged**Fail** Offside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Outer Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

**MOT #4**

2018-07-06 13:04

MOT test number

905096573499

Result

✓ Passed

Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both outer bushes (5.3.4 (a) (i))

Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both D bushes (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #3

2018-07-03 11:41

MOT test number

696419792188

Result

✗ Failed

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Fail Nearside Front Suspension component pin or bush excessively worn shock absorber (5.3.4 (a) (i))

Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both outer bushes (5.3.4 (a) (i))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both D bushes (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))

MOT #2

2017-06-15 11:37

MOT test number

564107869943

Result

✓ Passed



MOT #1	2017-06-15 11:37
MOT test number	711826847932
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Side repeater not working (1.4.A.2c)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 January 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-07-08
Last registration	2024-01-18
Complete history	See info



Registration #1	2014-07-08	11 mi
Registration #2	2017-06-15	32.800 mi
Registration #3	2017-06-15	32.800 mi
Registration #4	2018-07-03	43.766 mi
Registration #5	2018-07-06	43.768 mi
Registration #6	2019-06-20	52.981 mi
Registration #7	2019-07-17	52.997 mi
Registration #8	2019-07-17	52.997 mi
Registration #9	2019-07-17	52.997 mi
Registration #10	2019-07-17	52.997 mi
Registration #11	2019-07-17	52.997 mi
Registration #12	2019-07-17	52.997 mi
Registration #13	2019-07-17	52.997 mi
Registration #14	2019-07-17	52.997 mi
Registration #15	2019-07-17	52.997 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2265 mm
Height	2122 mm
Length	5189 mm
Wheel base	2500 mm
Kerb weight	1875 kg
Max. allowed weight	3400 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	891384B