





report date: 2024-03-28

#### General information

Mala.	FLAT
Make	FIAT
Model	500C ACTIVE
Colour	White
Year of manufacture	2012
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



MA12RYV

report date: 2024-03-28

#### Internet history

#### Entry 2

Date 2021-07-14

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

Date	2021-07-08	
Pictures	2	
Listing price	<u>View report</u>	





source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-27
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	12
Total items failed	8

MOT #13		2023-07-24 11:18
MOT test	number	114983224264
Result		✓ Passed
Next expiry date 2024-07		2024-07-27
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-07-24 10:46	
MOT test number	148048546004	
Result	<b>X</b> Failed	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification Exhaust has a major leak of exhaust gases (6.1.2 (a))		

MOT #11	2022-07-28 10:03
MOT test number	407652739115
Result	✓ Passed
MOT #10	2021-03-18 11:14
MOT test number	973126583400
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2021-03-17 11:18

MOT test number 642755319125

Result X Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2020-03-17 10:22

**MOT test number** 661407093259

**Result** ✓ Passed

**Advice** Front Exhaust mounting defective (6.1.2 (a))

**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #7** 2019-03-18 13:48

MOT test number 807990801363

**Result** ✓ Passed

MOT #6 2018-07-19 12:40

**MOT test number** 775240568035

Advice Nearside Rear Upper Suspension component pin or bush slightly worn shocker bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Upper Suspension component pin or bush slightly worn shocker bush (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



MA12RYV

report date: 2024-03-28

MOT #5 2017-07-21 10:50

MOT test number 192482211196

Result ✓ Passed

Advice Exhaust corroded

Advice Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #4 2016-07-22 11:13

**MOT test number** 878195800318

**Result** ✓ Passed

MOT #3 2016-03-29 15:03

**MOT test number** 503572045722

Result \rightarrow Passed

MOT #2 2016-03-29 10:07

**MOT test number** 528118325634

**Result** X Failed

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Front Lower Ball joint has excessive play (2.2.B.1f)

**Fail** Offside Headlamp aim too high (1.8)

**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #1** 2015-06-02 10:32

**MOT test number** 408573355103

**Result** ✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	27 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



MA12RYV

report date: 2024-03-28

Owner	history
OWITCE	Thocor y

,		
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	OK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-30
Last registration	2023-07-24
Complete history	See info



Registration #1	2012-03-30	24 mi
Registration #2	2015-06-02	55.937 mi
Registration #3	2016-03-29	69.800 mi
Registration #4	2016-03-29	69.800 mi
Registration #5	2016-07-22	70.097 mi
Registration #6	2017-07-21	74.584 mi
Registration #7	2018-07-19	77.083 mi
Registration #8	2019-03-18	78.559 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 6492127