



PEUGEOT



WR66YPE

report date: 2024-03-29

General information

Make	PEUGEOT
Model	BIPPER HDI PROFESSIONAL
Colour	White
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-16
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-25
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	0

MOT #8	2024-03-26 10:56
MOT test number	410993623009
Result	✓ Passed
Next expiry date	2025-03-25

MOT #7	2023-03-11 10:33
MOT test number	755915621168
Result	✓ Passed

MOT #6	2023-03-10 09:06
MOT test number	556106641943
Result	✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #5	2022-03-17 15:27
MOT test number	261208485019
Result	✓ Passed

**MOT #4** 2022-03-16 08:43**MOT test number** 462963774673**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Nearside Front Macpherson strut mounting fractured (5.3.3 (b) (ii))**MOT #3** 2021-03-01 13:29**MOT test number** 265473208681**Result** ✓ Passed**MOT #2** 2020-01-06 15:04**MOT test number** 904722187909**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #1** 2019-12-09 11:12**MOT test number** 588320111423**Result** ✗ Failed**MAJOR** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm inner and outer edges (5.2.3 (e))**MAJOR** Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**MAJOR** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
25 March 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	25 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	WR66YPE
Plate since	2024-03-29
Current registration	WR66YPE
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-11-30
Last registration	2024-03-26
Complete history	See info



Registration #1	2016-11-30	6 mi
Registration #2	2019-12-09	90.925 mi
Registration #3	2020-01-06	90.939 mi
Registration #4	2021-03-01	91.040 mi
Registration #5	2022-03-29	91.040 mi
Registration #6	2022-03-29	91.040 mi
Registration #7	2022-03-29	91.040 mi
Registration #8	2022-03-29	91.040 mi
Registration #9	2022-03-29	91.040 mi
Registration #10	2022-03-29	91.040 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1090 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	00016116577