



RENAULT

A055PZN

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27DCI 100 SWB P/V
Colour	Blue
Year of manufacture	2005
Top speed	97 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2021-01-27
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	38
Total items failed	13

MOT #18	2019-07-10 14:48
MOT test number	937830607874
Result	✓ Passed
Next expiry date	2021-01-27
Advice	Oil leak

MOT #17	2019-07-04 09:24
MOT test number	427625880257
Result	✗ Failed
MAJOR	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
MAJOR	Nearside Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))
Advice	Oil leak

**MOT #16**

2018-07-25 12:21

MOT test number

583867532799

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front wipers do not have a stop position
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #15

2018-07-25 09:52

MOT test number

457178346559

Result

✗ Failed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Front wipers do not have a stop position
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen wiper blade defective blades slightly smeary (3.4 (b) (i))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment nearside rear hand brake lever stuck forward making hand brake excessively high travel (1.1.6 (c))
- Advice** Front inner pads getting low
- MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**MOT #14** 2017-07-26 09:10**MOT test number** 793197523079**Result** ✓ Passed**Advice** Play in steering rack**Advice** Oil leak**Advice** Osr tyre worn on edges**MOT #13** 2017-07-26 09:10**MOT test number** 533038195052**Result** ✗ Failed**Advice** Osr tyre worn on edges**Advice** Play in steering rack**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Oil leak**MOT #12** 2016-07-25 11:14**MOT test number** 598354125808**Result** ✓ Passed**Advice** Damage to windscreen**Advice** Oil leak

**MOT #11** 2015-07-20 10:48**MOT test number** 177691405260**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Both wiper blades split on ends**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #10** 2014-07-28 16:03**MOT test number** 558599204243**Result** ✓ Passed**MOT #9** 2014-07-25 12:14**MOT test number** 768856204246**Result** ✗ Failed**Fail** Nearside Front Body has a sharp edge caused by corrosion (6.1.C.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2013-07-05 14:06**MOT test number** 307816783122**Result** ✓ Passed

**MOT #7** 2012-01-07 15:17**MOT test number** 798357002054**Result** ✓ Passed**MOT #6** 2012-01-06 11:10**MOT test number** 295836202029**Result** ✗ Failed

- Fail** Offside front brake binding (3.7.B.1)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Notice** Front brake discs worn

MOT #5 2010-10-30 12:52**MOT test number** 231773600368**Result** ✓ Passed**MOT #4** 2010-10-29 12:01**MOT test number** 974242500357**Result** ✗ Failed

- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #3 2009-10-20 09:01**MOT test number** 800363299231**Result** ✓ Passed

- Notice** Oil leak
- Advice** Offside Rear wheel bearing has slight play (2.6.2)
- Advice** Nearside Ball joint has slight play (2.2.B.1f)



MOT #2	2008-10-20 08:10
MOT test number	320024998461
Result	✓ Passed

MOT #1	2008-10-14 09:33
MOT test number	810588488255
Result	✗ Failed

Fail Offside Front Track rod end has had excessive heat applied (2.2.C.1e)



Tax & MOT check

✕
Untaxed

Tax expired:
20 November 2020

✕
MOT

Expired:
27 January 2021

Tax status

Expired at 20 November 2020

Days left

1256 days too late

MOT expiry date

27 January 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-10-19
Last registration	2019-07-10
Complete history	See info



Registration #1	2005-10-19	16 mi
Registration #2	2008-10-14	35.596 mi
Registration #3	2008-10-20	35.596 mi
Registration #4	2009-10-20	41.423 mi
Registration #5	2010-10-29	45.540 mi
Registration #6	2010-10-30	45.547 mi
Registration #7	2012-01-06	58.719 mi
Registration #8	2012-01-07	58.719 mi
Registration #9	2013-07-05	81.932 mi
Registration #10	2014-07-25	91.888 mi
Registration #11	2015-07-25	91.888 mi
Registration #12	2016-07-25	91.888 mi
Registration #13	2017-07-25	91.888 mi
Registration #14	2018-07-25	91.888 mi
Registration #15	2019-07-10	91.888 mi
Registration #16	2019-07-10	91.888 mi
Registration #17	2019-07-10	91.888 mi
Registration #18	2019-07-10	91.888 mi
Registration #19	2019-07-10	91.888 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Length	4782 mm
Kerb weight	1677 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C414332