



AK62UCA


report date: 2024-03-29

General information

Make	MINI
Model	COOPER AUTO COOPER
Colour	Red
Year of manufacture	2012
Top speed	119 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 2


Date	2021-09-26
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-25
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #9	2023-11-01 16:19
MOT test number	209096462477
Result	✓ Passed
Next expiry date	2024-11-01

MOT #8	2022-10-31 14:42
MOT test number	460793723049
Result	✓ Passed

MOT #7	2021-10-07 15:43
MOT test number	364237351619
Result	✓ Passed

**MOT #6** 2020-10-20 08:15**MOT test number** 185898620818**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #5** 2019-10-28 11:40**MOT test number** 586253487644**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2018-10-31 10:34**MOT test number** 727485825437**Result** ✓ Passed**MOT #3** 2017-10-24 19:09**MOT test number** 561509706146**Result** ✓ Passed**Advice** Nearside Front N/S/F tyre damage (outer side wall chunk missing - no cords visible or structure damage)**MOT #2** 2016-10-24 10:11**MOT test number** 789526518410**Result** ✓ Passed



MOT #1	2015-10-23 13:27
MOT test number	866799242078
Result	✓ Passed
Advice	Damage to nearside front outer tyre wall not to cords



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2024

✓  
**MOT**  
  
Expires:  
1 November 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	1 November 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-11-02
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2012-11-02	12 mi
Registration #2	2015-10-23	13.548 mi
Registration #3	2016-10-24	16.718 mi
Registration #4	2017-10-24	18.008 mi
Registration #5	2018-10-31	19.330 mi
Registration #6	2019-10-28	24.822 mi
Registration #7	2020-10-28	25.277 mi
Registration #8	2021-10-28	25.277 mi
Registration #9	2022-10-28	25.277 mi
Registration #10	2023-10-28	25.277 mi
Registration #11	2023-10-28	25.277 mi
Registration #12	2023-10-28	25.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	A540J360