



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 SE
Colour	Blue
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	229 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	31.4 mpg
CO2 emission	215 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-01-08
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	21
Total items failed	19

MOT #21	2023-08-11 14:39
MOT test number	746482422593
Result	✓ Passed
Next expiry date	2024-08-10

MOT #20	2023-08-11 14:39
MOT test number	779306327240
Result	✗ Failed
<div>Pass with rectification</div> Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #19	2023-01-19 13:59
MOT test number	663886040445
Result	✓ Passed

MOT #18	2021-11-01 15:44
MOT test number	935029123112
Result	✓ Passed

**MOT #17**

2021-10-28 10:49

MOT test number

606677519164

Result**✗ Failed**

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16

2020-09-24 15:48

MOT test number

790412931666

Result**✓ Passed****MOT #15**

2020-09-24 09:11

MOT test number

554727063027

Result**✗ Failed**

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #14

2019-09-24 14:16

MOT test number

730346871737

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #13** 2018-09-20 14:54**MOT test number** 560157345004**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-09-20 10:58**MOT test number** 389338795146**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11** 2017-09-19 12:30**MOT test number** 234565274930**Result** ✓ Passed**MOT #10** 2017-09-18 11:41**MOT test number** 432665208330**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Front registration plate character(s) likely to be misread (6.3.4b)**MOT #9** 2016-09-29 11:24**MOT test number** 727451598327**Result** ✓ Passed

**MOT #8**

2016-09-22 11:36

MOT test number

873562644586

Result

✗ Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**MOT #7**

2015-09-14 10:46

MOT test number

777705436338

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6**

2014-09-09 11:45

MOT test number

899152054225

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5**

2013-09-24 11:46

MOT test number

909167763211

Result

✓ Passed

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2012-09-25 10:30**MOT test number** 857729762263**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-08-25 16:43**MOT test number** 177907931299**Result** ✓ Passed**Notice** Several small cuts in outer wall of N/S/R tyre**MOT #2** 2010-09-09 13:49**MOT test number** 324592050217**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-09-01 10:28**MOT test number** 943644540210**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
16 February 2023

✓

MOT

Expires:
10 August 2024

Tax status	Expired at 16 February 2023
Days left	439 days too late
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-09-28
Last registration	2023-08-11
Complete history	See info



Registration #1	2007-09-28	19 mi
Registration #2	2010-09-01	27.054 mi
Registration #3	2010-09-09	27.341 mi
Registration #4	2011-08-25	35.662 mi
Registration #5	2012-09-25	45.555 mi
Registration #6	2013-09-24	53.583 mi
Registration #7	2014-09-09	60.577 mi
Registration #8	2015-09-14	67.611 mi
Registration #9	2016-09-22	74.544 mi
Registration #10	2016-09-29	74.546 mi
Registration #11	2017-09-18	81.088 mi
Registration #12	2017-09-19	81.089 mi
Registration #13	2018-09-18	81.089 mi
Registration #14	2018-09-18	81.089 mi
Registration #15	2018-09-18	81.089 mi
Registration #16	2018-09-18	81.089 mi
Registration #17	2018-09-18	81.089 mi
Registration #18	2018-09-18	81.089 mi
Registration #19	2018-09-18	81.089 mi
Registration #20	2018-09-18	81.089 mi
Registration #21	2018-09-18	81.089 mi
Registration #22	2018-09-18	81.089 mi
Registration #23	2018-09-18	81.089 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1692 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	4210618