



report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS JOHN COOPER WORKS ALL4
Colour	Black
Year of manufacture	2018
Top speed	145 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	231 BHP
Max. torque	350 Nm at 4.500 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	169 g/km
CO2 label	H



Internet history

Entry 1

Date	2022-07-12
Pictures	32
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-06
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #6	2023-07-06 08:44
MOT test number	475719972814
Result	✓ Passed
Next expiry date	2024-07-06
Advice	Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2023-06-30 14:40
MOT test number	933420120569
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.3mm worn outer edge (5.2.3 (e))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #4	2022-07-07 16:20
MOT test number	946246587304
Result	✓ Passed

**MOT #3** 2022-07-01 14:47**MOT test number** 845330914764**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Windscreen washer not working (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #2** 2022-02-09 09:31**MOT test number** 554376672700**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2021-01-27 15:39**MOT test number** 129386510432**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
6 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 <b>YL67LBK</b>
Plate since	2019-09-28
Current registration	 <b>YL67LBK</b>
Plate since	2019-09-28

More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-22
Last registration	2023-07-06
Complete history	<a href="#">See info</a>



Registration #1	2018-01-22	7 mi
Registration #2	2021-01-27	13.545 mi
Registration #3	2022-02-09	23.548 mi
Registration #4	2022-07-01	27.588 mi
Registration #5	2023-07-06	27.588 mi
Registration #6	2023-07-06	27.588 mi
Registration #7	2023-07-06	27.588 mi
Registration #8	2023-07-06	27.588 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2005 mm
Height	1557 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1540 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

G294H597