





report date: 2024-03-29

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Black
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	М



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history


Entry 1


 Date
 2021-09-01


 Pictures
 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-29
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	34
Total items failed	7

MOT #18	2024-01-24 13:08
MOT test number	792511674778
Result	✓ Passed
Next expiry date 2025-01-29	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #17	2024-01-24 11:32	
MOT test number	378937122927	
Result	X Failed	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, ingress of dirt (2.1.3 (g) (i))	but preventing the	
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3	.4 (b) (i))	

MOT #16	2023-01-30 09:43
MOT test number	267773262628
Result	✓ Passed
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

 MOT #15
 2022-01-28 12:28

 MOT test number
 557285289616

 Result
 ✓ Passed

 MOT #14
 2021-01-07 15:02

 MOT test number
 318851353900

 Result
 ✓ Passed

 Advice
 Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #12		2020-01-08 11:37
MOT test	number	555042507775
Result		✓ Passed
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cord	ds (5.2.3 (d) (i))
Advice	Offside Headlamp has a product on the lens but not seriously reducing lig	ht output (4.1.4 (b))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cor	rds (5.2.3 (d) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords	(5.2.3 (d) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #11 2020-01-08 11:37 **MOT test number** 816252567615 Result × Failed Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii)) Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice**


MOT #10	2019-01-03 13:23
MOT test	number 147470625578
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

MOT #9	2018-01-06 15:42
MOT test number	231325992086
Result	✓ Passed
MOT #8	2017-01-04 13:27
MOT test number	623866598034
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29



MOT #5	2015-01-05 16:19
MOT test number	896265705055
Result	✓ Passed
Notice Emissions too clean to test	

MOT #4		2014-01-03 15:04
MOT test	number	189803104440
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT test number

105165542344

Result

Notice Engine covers fitted obscuring some components in the engine bay

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2		2011-12-08 13:09
MOT test	number	277212041347
Result		✓ Passed
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2010-12-01 15:05
MOT test number	734905230317
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt Advice Parking brake lever has little reserve travel (3.1.6b)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



funda scincos

SH57SCH

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this AUDI had different number plates.

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-11
Last registration	2024-01-24
Complete history	See info



Registration #1	2007-09-11	11 mi
Registration #2	2010-12-01	34.861 mi
Registration #3	2011-12-08	50.580 mi
Registration #4	2012-12-10	64.922 mi
Registration #5	2014-01-03	75.588 mi
Registration #6	2015-01-05	85.023 mi
Registration #7	2016-01-08	92.838 mi
Registration #8	2016-01-08	92.839 mi
Registration #9	2017-01-04	100.113 mi
Registration #10	2018-01-06	106.188 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14