



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XS
Colour	Silver
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.8 mpg
CO2 emission	228 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-06-18
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-17
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	35
Total items failed	2

MOT #18	2023-08-18 10:19
---------	------------------

MOT test number	785498958425
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-17
------------------	------------

- Minor

Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Offside Front Slight Movement In Steering Rack Mounting Bush
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor

Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement
Arm Rear Bush (5.3.4 (a) (i))

**MOT #17**

2023-05-22 15:16

MOT test number

545498971787

Result**✗ Failed****Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**DANGEROUS** Front Prop shaft joint so worn it is likely to fail Prop Shaft Rear Joint (6.1.7 (c) (ii))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Slight Movement In Steering Rack Mounting Bushes**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Arm Rear Bush (5.3.4 (a) (i))**DANGEROUS** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #16**

2022-10-05 11:07

MOT test number

782363426917

Result**✗ Failed****MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))**Minor** Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))**MOT #15**

2021-08-13 09:14

MOT test number

991346316101

Result**✓ Passed****MOT #14**

2021-08-13 09:14

MOT test number

256193875435

Result**✗ Failed****Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #13**

2020-08-15 11:05

MOT test number

727545030188

Result**✓ Passed**

**MOT #12** 2020-08-14 12:31**MOT test number** 408233334398**Result** ✗ Failed**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #11** 2019-04-23 07:56**MOT test number** 599570364020**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2018-05-02 07:50**MOT test number** 771236194264**Result** ✓ Passed**MOT #9** 2017-05-04 08:42**MOT test number** 396227828720**Result** ✓ Passed**MOT #8** 2017-05-04 08:42**MOT test number** 962542814960**Result** ✗ Failed**Pass with rectification** Nearside Headlamp has a product on the light source so that the light output is severely reduced (1.7.5a)**MOT #7** 2016-04-27 11:37**MOT test number** 783805950012**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear pads getting low

**MOT #6** 2015-04-29 11:35**MOT test number** 186369515134**Result** ✓ Passed**MOT #5** 2014-05-06 12:52**MOT test number** 568966924140**Result** ✓ Passed**MOT #4** 2013-05-07 09:14**MOT test number** 107837823124**Result** ✓ Passed**Notice** Engine Has A Plastic Cover Fitted Obscuring Some Engine Components**Notice** Both Rear Tyres Starting To Perish**Notice** Slight Play In Both Steering Arms**MOT #3** 2012-05-16 11:50**MOT test number** 997257532151**Result** ✓ Passed**MOT #2** 2011-10-28 11:38**MOT test number** 498501601455**Result** ✓ Passed**MOT #1** 2010-11-26 16:14**MOT test number** 464110730338**Result** ✓ Passed**Notice** Handbrake travel slightly long.



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-11-26
Last registration	2023-08-18
Complete history	See info



Registration #1	2007-11-26	28 mi
Registration #2	2010-11-26	18.428 mi
Registration #3	2011-10-28	22.813 mi
Registration #4	2012-05-16	23.931 mi
Registration #5	2013-05-07	32.127 mi
Registration #6	2014-05-06	39.952 mi
Registration #7	2015-04-29	49.093 mi
Registration #8	2016-04-27	57.286 mi
Registration #9	2017-05-04	64.898 mi
Registration #10	2017-05-04	64.898 mi
Registration #11	2018-05-04	72.510 mi
Registration #12	2019-05-04	80.122 mi
Registration #13	2020-05-04	87.734 mi
Registration #14	2021-05-04	95.346 mi
Registration #15	2022-05-04	102.958 mi
Registration #16	2023-05-04	110.570 mi
Registration #17	2024-05-04	118.182 mi
Registration #18	2025-05-04	125.794 mi
Registration #19	2026-05-04	133.406 mi
Registration #20	2027-05-04	141.018 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2670 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB6056786