




report date: 2024-03-29

## General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Grey
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-27
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	18
Total items failed	6

MOT #14	2023-07-28 15:00
MOT test number	482660993784
Result	✓ Passed
Next expiry date	2024-07-27

MOT #13	2022-03-30 15:48
MOT test number	851218288450
Result	✓ Passed

MOT #12	2022-03-30 10:19
MOT test number	164276479329
Result	✗ Failed
<div><div>Advice</div> Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))</div> <div><div>DANGEROUS</div> Tyre tread depth below requirements of 1.6mm both front (5.2.3 (e))</div> <div><div>MAJOR</div> Exhaust system insecure front mount broken (6.1.2 (a))</div>	

MOT #11	2021-03-30 11:58
MOT test number	911777254674
Result	✓ Passed

**MOT #10** 2020-10-27 07:51**MOT test number** 646420876425**Result** ✓ Passed**MOT #9** 2020-10-27 07:51**MOT test number** 157642867259**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2020-05-20 15:55**MOT test number** 839641350274**Result** ✓ Passed**MOT #7** 2019-04-09 11:22**MOT test number** 810630141004**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2018-04-16 15:36**MOT test number** 644138176411**Result** ✓ Passed

**MOT #5** 2018-04-16 10:28**MOT test number** 108735938028**Result** ✗ Failed

- Fail** Nearside Front Inner brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front Inner Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front Inner brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Offside Front Inner Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

**MOT #4** 2017-04-18 10:14**MOT test number** 406500486535**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Power steering component(s) has slight seepage from a component Slight leak on power steering rack. (2.3.3b)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Power steering pipe(s) or hose(s) slightly corroded Pipe on rear of power steering rack (2.3.2)

**MOT #3** 2017-04-18 08:50**MOT test number** 443764686550**Result** ✗ Failed**Advice** Offside Front Power steering component(s) has slight seepage from a component Slight leak on power steering rack. (2.3.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Power steering pipe(s) or hose(s) slightly corroded Pipe on rear of power steering rack (2.3.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #2** 2016-04-13 10:38**MOT test number** 955997348746**Result** ✓ Passed**MOT #1** 2015-04-13 11:41**MOT test number** 225443905116**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
27 July 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	27 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-04-20
Last registration	2023-07-28
Complete history	<a href="#">See info</a>



Registration #1	2012-04-20	18 mi
Registration #2	2015-04-13	10.557 mi
Registration #3	2016-04-13	14.256 mi
Registration #4	2017-04-18	18.325 mi
Registration #5	2017-04-18	18.325 mi
Registration #6	2018-04-16	21.124 mi
Registration #7	2018-04-16	21.124 mi
Registration #8	2019-04-09	24.395 mi
Registration #9	2019-04-09	24.395 mi
Registration #10	2019-04-09	24.395 mi
Registration #11	2019-04-09	24.395 mi
Registration #12	2019-04-09	24.395 mi
Registration #13	2019-04-09	24.395 mi
Registration #14	2019-04-09	24.395 mi
Registration #15	2019-04-09	24.395 mi
Registration #16	2019-04-09	24.395 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1097033