



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	E E220 CDI ELEGANCE
Colour	Black
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	8.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H





## MOT history

MOT expiry date	2024-08-31
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	14
Total items failed	13

MOT #17	2023-09-01 10:56
MOT test number	383804278652
Result	✓ Passed
Next expiry date	2024-08-31

MOT #16	2023-08-30 09:40
MOT test number	928187618109

Result	✗ Failed
--------	----------

**Fail** Nearside Front Inner Suspension arm pin or bush excessively worn Reaction arm bush (5.3.4 (a) (i))

**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

**Fail** Nearside Rear Outer Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #15** 2022-08-23 14:13**MOT test number** 982661902928**Result** ✓ Passed**MOT #14** 2021-08-25 09:30**MOT test number** 281186634490**Result** ✓ Passed

- Advice** Nearside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13** 2020-08-27 15:14**MOT test number** 246214550230**Result** ✓ Passed**MOT #12** 2019-08-16 13:53**MOT test number** 469948941765**Result** ✓ Passed**MOT #11** 2018-08-17 08:59**MOT test number** 420668684828**Result** ✓ Passed

- Advice** Nearside Front Suspension arm ball joint has slight play front arm (5.3.4 (a) (i))

**MOT #10** 2018-08-17 08:59**MOT test number** 860192602710**Result** ✗ Failed

- Advice** Nearside Front Suspension arm ball joint has slight play front arm (5.3.4 (a) (i))
- Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2017-09-01 07:01**MOT test number** 750412555695**Result** ✓ Passed**MOT #8** 2016-08-17 13:56**MOT test number** 889307223091**Result** ✓ Passed**Advice** Engine covers and under body covers fitted obscuring some testable items**MOT #7** 2016-08-15 11:47**MOT test number** 638958552755**Result** ✗ Failed**Advice** Engine covers and under body covers fitted obscuring some testable items**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #6** 2014-08-26 16:05**MOT test number** 146148134222**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2013-09-05 10:53**MOT test number** 295208643212**Result** ✓ Passed

**MOT #4** 2012-08-31 14:56**MOT test number** 615484142201**Result** ✓ Passed**MOT #3** 2012-08-30 09:03**MOT test number** 147603442252**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2011-08-31 08:08**MOT test number** 397993141228**Result** ✓ Passed**MOT #1** 2011-08-27 08:40**MOT test number** 577529031281**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>KW08NBD</b>
Plate since	2019-03-29
Current registration	<b>KW08NBD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-27
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2008-05-27	18 mi
Registration #2	2011-08-27	27.531 mi
Registration #3	2011-08-31	27.574 mi
Registration #4	2012-08-30	32.593 mi
Registration #5	2012-08-31	32.593 mi
Registration #6	2013-09-05	38.097 mi
Registration #7	2014-08-26	45.479 mi
Registration #8	2016-08-15	58.780 mi
Registration #9	2016-08-17	58.785 mi
Registration #10	2019-05-29	75.377 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi

More info >



Dimensions & weight

Width	1822 mm
Height	1483 mm
Length	4852 mm
Wheel base	2833 mm
Kerb weight	1785 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64682130238396