



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 F SE SPORT
Colour	Grey
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Gas / Diesel
Consumption city	24.1 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.8 mpg
CO2 emission	206 g/km
CO2 label	K





## Internet history

### Entry 4

Date	2021-10-28
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3



Date	2021-10-14
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date	2021-09-14
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1


Date	2021-08-31
------	------------

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-01
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #16	2023-07-31 09:50
MOT test number	491508402689
Result	✓ Passed
Next expiry date	2024-08-01
Advice	Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #15	2022-07-23 11:26
MOT test number	934237761338
Result	✓ Passed
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14	2021-08-02 08:06
MOT test number	524435571134
Result	✓ Passed

MOT #13	2020-12-04 11:02
MOT test number	774642008934
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2019-11-20 09:48**MOT test number** 496295998795**Result** ✓ Passed**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2018-11-23 12:46**MOT test number** 338012173312**Result** ✓ Passed**MOT #10** 2018-11-14 15:33**MOT test number** 211888674816**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #9** 2017-12-13 11:08**MOT test number** 408419324438**Result** ✓ Passed**MOT #8** 2016-11-22 14:43**MOT test number** 721541957252**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-12-09 09:40**MOT test number** 281680715721**Result** ✓ Passed**MOT #6** 2014-11-25 10:10**MOT test number** 767679924342**Result** ✓ Passed**MOT #5** 2013-11-26 16:28**MOT test number** 447970233476**Result** ✓ Passed**MOT #4** 2013-11-26 10:44**MOT test number** 877120233304**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #3** 2012-11-22 09:46**MOT test number** 406777022410**Result** ✓ Passed**MOT #2** 2011-11-22 09:33**MOT test number** 617076121333**Result** ✓ Passed**MOT #1** 2010-12-14 13:49**MOT test number** 840868040332**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
1 August 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	1 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 385,00,-
<b>Single six month payment</b>	£ 211,75,-
<b>Total payable by 12 monthly instalments</b>	£ 404,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>AD57WMY</b>
Plate since	2019-09-28
Current registration	<b>AD57WMY</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-30
Last registration	2023-07-31
Complete history	<a href="#">See info</a>



Registration #1	2008-01-30	29 mi
Registration #2	2010-12-14	25.253 mi
Registration #3	2011-11-22	32.005 mi
Registration #4	2012-11-22	35.760 mi
Registration #5	2013-11-26	40.107 mi
Registration #6	2013-11-26	40.107 mi
Registration #7	2014-11-25	44.779 mi
Registration #8	2015-12-09	48.624 mi
Registration #9	2016-11-22	51.685 mi
Registration #10	2017-12-13	54.744 mi
Registration #11	2018-11-14	57.814 mi
Registration #12	2019-01-29	59.377 mi
Registration #13	2019-01-29	59.377 mi
Registration #14	2019-01-29	59.377 mi
Registration #15	2019-01-29	59.377 mi
Registration #16	2019-01-29	59.377 mi
Registration #17	2019-01-29	59.377 mi
Registration #18	2019-01-29	59.377 mi
Registration #19	2019-01-29	59.377 mi
Registration #20	2019-01-29	59.377 mi
Registration #21	2019-01-29	59.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	4002353