

Ford



General information

| Make | FORD |
|---------------------|--------------------|
| Model | TRANSIT 290 LR P/V |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 10 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 114 kW / 155 HP / 98 BHP |
|-------------------------|--------------------------|
| Max. torque | 330 Nm at 1.600 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 33.6 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 186 g/km |
| CO2 label | J |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2022-06-18 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

Entry 1

| Date | 2021-08-27 |
|---------------|-------------|
| Pictures | 19 |
| Listing price | View report |









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-10-08 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 2 |

| MOT #8 | 2023-10-09 10:25 |
|---|------------------|
| MOT test number | 457294578744 |
| Result | 🗸 Passed |
| Next expiry date | 2024-10-08 |
| Advice Nearside Rear Nail in tyre | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened BOTH corroded on inner face (1.1.14 (a) (ii)) | |
| Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush worn (5.3.4 (a) (i)) | |
| Advice Steering wheel knob fitted | |

| MOT #7 | 2022-09-21 09:50 |
|-----------------|------------------|
| MOT test number | 665371909787 |
| Result | ✓ Passed |

| MOT #6 | 2021-09-22 09:47 |
|--|-------------------------------|
| MOT test number | 927023715310 |
| Result | ✓ Passed |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in (i)) | excessive movement (5.3.4 (a) |





| MOT #5 | | 2020-11-21 10:15 |
|--------------------------|---|------------------|
| MOT test number | | 744143391440 |
| Result | | ✓ Passed |
| Advice Offside Front Tyr | re worn close to legal limit/worn on edge (5.2.3 (e)) | |
| МОТ #4 | | 2019-10-17 13:15 |
| MOT test number | | 120012083054 |
| Result | | 🗙 Failed |
| Fail Engine MIL inoperat | tive or indicates a malfunction (8.2.1.2 (h)) | |
| МОТ #3 | | 2019-06-13 12:04 |
| MOT test number | | 283969414288 |
| Result | | ✓ Passed |
| MOT #2 | | 2019-06-13 12:04 |
| MOT test number | | 739956830246 |
| Result | | 🗙 Failed |
| Pass with rectification | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| | | |

| | 2010 00 14 10.43 |
|-----------------|------------------|
| MOT test number | 283241618843 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|---------------------------|--|
| 1 June 2024 Tax status | Expires: 8 October 2024 Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 8 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---|-------|
| Date | | |
| Category | | ARMP |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | AT I |
| Date | | * |
| Category | AMA | |
| Туре | No. Contraction of the second s | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ****** | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-06-04 |
| Last registration | 2023-10-09 |
| Complete history | See info |



| Registration #1 | 2015-06-04 | 23 mi |
|------------------|------------|------------|
| Registration #2 | 2018-06-14 | 51.029 mi |
| Registration #3 | 2019-06-13 | 62.595 mi |
| Registration #4 | 2019-06-13 | 62.595 mi |
| Registration #5 | 2019-10-17 | 64.989 mi |
| Registration #6 | 2020-11-21 | 66.164 mi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.117 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 90% |
| Pedestrian | 48% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2272 mm |
| Height | 1922 mm |
| Length | 4972 mm |
| Wheel base | 3300 mm |
| Kerb weight | 1817 kg |
| Max. allowed weight | 2900 kg |
| Additional information | |
| Fuel tank capacity | 80 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |