



report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI EXCLUSIVE EGS GRAND PICASSO
Colour	Blue
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	270 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg





Internet history

Entry 4

Date	2021-10-31
Pictures	38
Listing price	View report



source: autotrader.co.uk

Entry 3


Date	2021-10-17
Pictures	38
Listing price	View report



source: autotrader.co.uk

Entry 2

Date	2021-09-19
Pictures	38
Listing price	View report



source: autotrader.co.uk

Entry 1


Date	2021-09-05
------	------------

Pictures

38

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2022-12-20 13:51
MOT test number	222730988290
Result	✓ Passed
Next expiry date	2023-12-19
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

MOT #17	2022-12-16 10:53
MOT test number	789646301574
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Central Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #16	2021-11-26 12:30
MOT test number	604065324059
Result	✓ Passed

**MOT #15** 2020-12-18 16:47**MOT test number** 661919269357**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2020-12-18 16:47**MOT test number** 449458148250**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #13** 2019-12-16 16:18**MOT test number** 758921455486**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

**MOT #12** 2018-12-18 14:45**MOT test number** 745591318872**Result** ✓ Passed**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2018-12-18 14:45**MOT test number** 470741466421**Result** ✗ Failed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #10** 2017-11-28 10:59**MOT test number** 932961982986**Result** ✓ Passed**MOT #9** 2016-11-15 12:58**MOT test number** 632633360246**Result** ✓ Passed

**MOT #8** 2016-11-11 12:56**MOT test number** 803077913631**Result** ✗ Failed**Fail** Rear Direction indicator incorrect colour Both sides (1.4.A.2f)**Fail** Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**MOT #7** 2015-12-12 12:21**MOT test number** 433846541938**Result** ✓ Passed**MOT #6** 2015-06-19 14:40**MOT test number** 678430775126**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #5** 2014-12-02 17:31**MOT test number** 487846734490**Result** ✓ Passed**MOT #4** 2014-04-23 15:54**MOT test number** 978833114169**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components

**MOT #3** 2014-04-23 15:54**MOT test number** 966043514114**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-04-20 14:33**MOT test number** 497680313173**Result** ✓ Passed**MOT #1** 2013-04-20 13:17**MOT test number** 926630513175**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-04-30
Last registration	2022-12-20
Complete history	See info



Registration #1	2010-04-30	21 mi
Registration #2	2013-04-20	57.825 mi
Registration #3	2013-04-20	57.825 mi
Registration #4	2014-04-23	86.829 mi
Registration #5	2014-12-02	106.393 mi
Registration #6	2015-06-19	113.868 mi
Registration #7	2015-12-12	123.557 mi
Registration #8	2016-11-11	136.256 mi
Registration #9	2016-11-15	136.258 mi
Registration #10	2017-11-28	138.278 mi
Registration #11	2018-12-18	140.788 mi
Registration #12	2019-05-20	151.277 mi
Registration #13	2019-05-20	151.277 mi
Registration #14	2019-05-20	151.277 mi
Registration #15	2019-05-20	151.277 mi
Registration #16	2019-05-20	151.277 mi
Registration #17	2019-05-20	151.277 mi
Registration #18	2019-05-20	151.277 mi
Registration #19	2019-05-20	151.277 mi
Registration #20	2019-05-20	151.277 mi
Registration #21	2019-05-20	151.277 mi
Registration #22	2019-05-20	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1620 kg
Max. allowed weight	2320 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DYXC4029246