



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 VTR
Colour	Red
Year of manufacture	2009
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	143 g/km
CO2 label	F





## MOT history

MOT expiry date	2024-02-17
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	21
Total items failed	14

MOT #19	2023-02-18 12:44
MOT test number	890851370470
Result	✓ Passed
Next expiry date	2024-02-17
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #18	2022-02-10 14:58
MOT test number	184554341764
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Non obligatory mirror damaged
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-02-13 11:31
MOT test number	799812767761
Result	✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2021-02-13 11:31**MOT test number** 543274885325**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2020-01-27 10:07**MOT test number** 147430952395**Result** ✓ Passed**MOT #14** 2019-04-18 15:14**MOT test number** 397548357560**Result** ✓ Passed**MOT #13** 2019-04-11 14:15**MOT test number** 883941870945**Result** ✗ Failed**MAJOR** Horn sound not in accordance with requirements (7.7 (c))**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #12** 2018-03-23 07:19**MOT test number** 233319438008**Result** ✓ Passed**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Under trays fitted restricting access testable items**Advice** Front Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #11** 2018-03-23 07:19**MOT test number** 722662123494**Result** ✗ Failed**Advice** Front Shock absorber has slight corrosion to the casing (2.7.2a)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Under trays fitted restricting access testable items**MOT #10** 2017-04-06 10:56**MOT test number** 832075994917**Result** ✓ Passed**MOT #9** 2017-04-05 11:10**MOT test number** 737424140446**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #8** 2016-04-11 15:08**MOT test number** 510340589045**Result** ✓ Passed**MOT #7** 2016-04-11 08:31**MOT test number** 133866606438**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Rear Upper Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #6** 2015-03-20 14:29**MOT test number** 159369075474**Result** ✓ Passed**MOT #5** 2015-03-20 09:42**MOT test number** 576139175000**Result** ✗ Failed**Fail** Offside Front Front constant velocity joint is insecure (2.5.C.1b)**Notice** All tyres cracking on walls,**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2014-04-18 15:39**MOT test number** 568768104104**Result** ✓ Passed**MOT #3** 2013-12-20 10:32**MOT test number** 465674053475**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #2	2013-12-19 13:49
MOT test number	539023553322
Result	✗ Failed
<div><div>Advice</div>Front registration plate deteriorated but not likely to be misread (6.3.1d)</div>	
<div><div>Fail</div>Nearside Rear Direction indicator incorrect colour (1.4.A.2f)</div>	
<div><div>Fail</div>Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)</div>	
<div><div>Fail</div>Offside Rear rear brake excessively fluctuating (3.7.B.3)</div>	
<div><div>Fail</div>Offside Rear Direction indicator incorrect colour (1.4.A.2f)</div>	
<div><div>Fail</div>Offside Rear rear brake binding (3.7.B.1)</div>	
MOT #1	2012-12-31 13:03
MOT test number	738526262366
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-12-31
Last registration	2023-02-18
Complete history	<a href="#">See info</a>



Registration #1	2009-12-31	18 mi
Registration #2	2012-12-31	12.610 mi
Registration #3	2013-12-19	27.567 mi
Registration #4	2013-12-20	27.567 mi
Registration #5	2014-04-18	27.580 mi
Registration #6	2015-03-20	31.300 mi
Registration #7	2015-03-20	31.300 mi
Registration #8	2016-04-11	41.420 mi
Registration #9	2016-04-11	41.420 mi
Registration #10	2017-04-05	50.038 mi
Registration #11	2018-04-05	50.038 mi
Registration #12	2018-04-05	50.038 mi
Registration #13	2018-04-05	50.038 mi
Registration #14	2018-04-05	50.038 mi
Registration #15	2018-04-05	50.038 mi
Registration #16	2018-04-05	50.038 mi
Registration #17	2018-04-05	50.038 mi
Registration #18	2018-04-05	50.038 mi
Registration #19	2018-04-05	50.038 mi
Registration #20	2018-04-05	50.038 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	990 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST36122073