



YY09AXP

report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	-
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



MOT history

MOT #14

2021-02-10 12:35

MOT test number

635033918019

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Nail in tyre**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MAJOR** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13

2020-02-07 09:38

MOT test number

529548584002

Result

✓ Passed

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12** 2018-12-04 13:31**MOT test number** 642925894205**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #11** 2018-12-04 13:31**MOT test number** 665733632197**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**MOT #10** 2017-12-07 10:34**MOT test number** 426195269208**Result** ✓ Passed**MOT #9** 2017-05-08 10:01**MOT test number** 914181390253**Result** ✓ Passed**Advice** Offside Front tyre bald on the inner edge**Advice** Oil leak

**MOT #8** 2016-05-09 15:26**MOT test number** 780612527507**Result** ✓ Passed**Advice** Rear exhaust deteriorated**Advice** Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)**Advice** Engine oil leak**MOT #7** 2016-05-06 14:00**MOT test number** 489353059257**Result** ✗ Failed**Fail** Power steering inoperative (2.3.3a)**Advice** Battery warning light on**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear exhaust deteriorated**Advice** Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)**Advice** Engine oil leak**MOT #6** 2015-04-09 14:37**MOT test number** 395119295053**Result** ✓ Passed**Advice** Offside Rear Brake hose slightly chafed (3.6.B.4d)

**MOT #5** 2015-04-07 15:17**MOT test number** 105967895435**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Brake hose slightly chafed (3.6.B.4d)**Fail** Offside Rear Brake hose has insufficient room to move, resulting in fouling on any part (3.6.B.4a)**MOT #4** 2014-07-07 11:31**MOT test number** 378838984198**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-04-29 16:00**MOT test number** 717319013189**Result** ✓ Passed**Notice** Rear silencer corroding**MOT #2** 2013-04-29 16:00**MOT test number** 957519613152**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Rear silencer corroding**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2012-04-26 16:04**MOT test number** 869207412117**Result** ✓ Passed**Notice** Rear silencer corroding



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YY09AXP
Plate since	2024-03-29
Current registration	YY09AXP
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-04-30
Last registration	2021-02-10
Complete history	See info



Registration #1	2009-04-30	17 mi
Registration #2	2012-04-26	29.244 mi
Registration #3	2013-04-29	38.398 mi
Registration #4	2014-07-07	48.800 mi
Registration #5	2015-04-07	57.675 mi
Registration #6	2015-04-09	57.755 mi
Registration #7	2016-05-06	70.558 mi
Registration #8	2016-05-06	70.558 mi
Registration #9	2016-05-06	70.558 mi
Registration #10	2016-05-06	70.558 mi
Registration #11	2016-05-06	70.558 mi
Registration #12	2016-05-06	70.558 mi
Registration #13	2016-05-06	70.558 mi
Registration #14	2016-05-06	70.558 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694