






report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 CC GT
Colour	Black
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP	
Max. torque	160 Nm at 4.250 rpm	
Engine capacity	1.598 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	32.1 mpg	
Consumption extra urban	53.3 mpg	
Consumption combined	43.5 mpg	
CO2 emission	150 g/km	
CO2 label	F	



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-01-21


Pictures 33

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-11
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	16
Total items failed	9

MOT #16	2023-09-09 09:58
MOT test number	471725952839
Result	✓ Passed
Next expiry date	2024-09-11
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #15 2023-09-01 13:59 716112821117 **MOT** test number Result × Failed Fail Engine MIL inoperative or indicates a malfunction white smoke from exhaust and overheating? (8.2.1.2 (h)) Minor Offside Rear Tyre obviously under inflated (5.2.3 (I)) Advice Coolant leak Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Minor Offside Front Tyre obviously under inflated (5.2.3 (I))

MOT #14		2022-09-12 09:09
MOT test	number	744561029875
Result		✓ Passed
Advice	Driver's view Items removed from driver's view prior to test air freshener (3	.1 (a) (ii))

CarCheck.co.uk page 3/13



BN10WJY

report date: 2024-03-28

MOT #13 2022-09-09 11:48

MOT test number 903737347254

Result X Failed

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Advice Driver's view Items removed from driver's view prior to test air freshener (3.1 (a) (ii))

MOT #12 2021-08-28 11:08

MOT test number 571139720069

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

MOT #11 2021-08-27 09:01

MOT test number 443531316154

Result X Failed

Fail Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

Advice Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

CarCheck.co.uk page 4/13



MOT #10 2020-09-04 16:20

MOT test number 814027473167

MOT #9 2019-06-13 14:19

MOT test number 543936407793

Result ✓ Passed

MOT #8 2018-06-14 16:01

MOT test number 400251317362

Result \(\sqrt{Passed} \)

MOT #7 2018-06-14 16:01

MOT test number 919254932093

Result X Failed

Pass with rectification Offside Front Position lamp not working main light (4.2.1 (a))

Pass with rectification Nearside Rear Registration plate lamp does not illuminate simultaneously with

the position lamps (4.7.2 (a))

Pass with rectification Offside Front Position lamp not working side light (4.2.1 (a))

MOT #6 2017-06-07 13:30

MOT test number 995068015993

Result ✓ Passed

MOT #5 2016-06-15 12:55

MOT test number 971674019150

MOT #4 2015-03-27 15:19

MOT test number 196286185084

Result
✓ Passed

CarCheck.co.uk page 5/13



MOT #32014-03-18 10:55MOT test number647677274071Result✓ PassedMOT #22013-11-13 12:29MOT test number836247113324Result✓ PassedNoticeBoth front tyres have cuts to sidewalls.

MOT #1	2013-03-28 11:11
MOT test number	155757883425
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	11 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



BN10WJY

report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincore

BN10WJY

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. door of plates

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



BN10WJY

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-26
Last registration	2023-09-09
Complete history	See info



Registration #1	2010-03-26	23 mi
Registration #2	2013-03-28	28.031 mi
Registration #3	2013-11-13	33.932 mi
Registration #4	2014-03-18	33.988 mi
Registration #5	2015-03-27	42.056 mi
Registration #6	2016-06-15	48.437 mi
Registration #7	2017-06-07	51.184 mi
Registration #8	2018-06-14	53.305 mi
Registration #9	2018-06-14	53.305 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 au

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionir
S0295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1749 mm
Height	1387 mm
Length	4037 mm
Wheel base	2540 mm
Kerb weight	1417 kg
Max. allowed weight	1709 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number FHBW0819629