





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	206 D TURBO HDI (110BHP)
Colour	Silver
Year of manufacture	2004
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.3 mpg
Consumption extra urban	67.2 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/15



Internet history

-		-		1
п	L	ΓV	,	т.

Entry 1	
Date	2022-01-17
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-12-22
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	31
Total items failed	18

MOT #25	2023-12-19 12:42
MOT test number	893512808321
Result	✓ Passed
Next expiry date	2024-12-22
Advice Rear Inner offside and nearside rear inner sidesills slightly corroded	

MOT #	24	2023-11-27 15:10
MOT te	st number	132955363078
Result		<b>X</b> Failed
Fail	Offside Side repeater not working (4.4.1 (a) (ii))	
Advid	Nearside Rear Tyre worn close to legal limit/worn on edge on 3 mm tread de	epth (5.2.3 (e))
Fail	Front Lower Anti-roll bar linkage ball joint excessively worn offside and nearsid	e (5.3.4 (a) (i))
Fail	Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Fail</b> gaiters	Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ing split (5.3.4 (b) (ii))	gress of dirt both
Fail	Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #23

MOT test number

Result

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #22

MOT test number

Result

Advice N/s/f anti roll bar link has slight play

Advice Fuel tank mounting strap corroding

MOT test number

Result

Advice N/s/f anti roll bar link has slight play

Pass with rectification Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))

Advice Fuel tank mounting strap corroding

MOT #20

MOT test number

244283085253

Result

Advice Fuel tank strap corroded

Advice Spare wheel rim corroded

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #19** 2020-12-14 17:07 **MOT** test number 283446160530 Result × Failed Fail Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Nearside Front Headlamp aim not tested (4.1.2 (b)) **Advice** Spare wheel rim corroded Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail **Advice** Fuel tank strap corroded

MOT test number

Soloria Secult

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust emissions - minimum requirements only just met

Advice Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))

MOT #17

MOT test number

Result

Advice Rear exhaust bracket broken

MOT test number
973230120036

Result

Advice O/s/f tyre heavily perished / cracked

Advice Nearside Front Play in steering rack inner joint(s)

Advice Front brake discs corroded

CarCheck.co.uk page 5/15



**MOT #14** 

Result

FV04PGZ

report date: 2024-03-29

2015-12-10 13:32

× Failed

 MOT #15
 2016-11-23 10:56

 MOT test number
 449722500092

 Result
 ✓ Passed

**MOT test number** 883704595395

**Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)

**MOT #13** 2015-12-10 09:27

MOT test number 540646888944

Result X Failed

**Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)

**Advice** Offside number plate bulb dim

Fail Fuel system component leaking filter housing (7.2.3)

MOT #12 2014-12-15 09:20

MOT test number 226109944302

**Notice** Heavy corrosion to fuel tank strap

**MOT #11** 2014-12-15 09:20

**MOT test number** 928179744313

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

**Notice** Heavy corrosion to fuel tank strap

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #10 2013-12-19 09:43 457573253425 **MOT** test number ✓ Passed Result **MOT** #9 2013-12-19 09:43 **MOT** test number 909483953312 Result × Failed Pass with rectification Offside Headlamp aim too high (1.8) **Pass with rectification** Nearside Headlamp aim too high (1.8)

MOT #8

MOT test number

478102323064

Result

Notice Rear silencer deteriorated

MOT test number

Result

Notice Rear silencer deteriorated

Pass with rectification Nearside Headlamp aim too low (1.8)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Headlamp aim too low (1.8)

MOT #6

MOT test number

625090232005

Result

Advice Offside Side repeater slightly discoloured (1.4.A.2f)

Advice Nearside Side repeater slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 7/15



report date: 2024-03-29

**MOT #5** 2011-01-27 15:36

109867421044 **MOT** test number

Result ✓ Passed

**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)

**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Nearside Side repeater slightly discoloured (1.4.A.2f)

**Advice** 

**Advice** (2.4.G.2)

**MOT #4** 2010-01-26 11:14

Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement

**MOT** test number 114596620466

Result Passed

**MOT** #3 2009-07-20 09:26

**MOT test number** 770791209233

Result ✓ Passed

MOT #2 2008-07-29 09:23

621281618234 **MOT** test number

Result ✓ Passed

**MOT #1** 2007-06-29 09:45

**MOT** test number 871170187127

✓ Passed Result

CarCheck.co.uk page 8/15



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	22 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



furthe scinors

FV04PGZ

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. about of pliates

CarCheck.co.uk page 12/15



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-06-30
Last registration	2023-12-19
Complete history	See info



Registration #1	2004-06-30	13 mi
Registration #2	2007-06-29	37.061 mi
Registration #3	2008-07-29	48.049 mi
Registration #4	2009-07-20	58.178 mi
Registration #5	2010-01-26	64.203 mi
Registration #6	2011-01-27	71.423 mi
Registration #7	2012-01-30	74.366 mi
Registration #8	2013-01-22	78.327 mi
Registration #9	2013-12-19	82.641 mi
Registration #10	2014-12-15	85.728 mi
Registration #11	2015-12-10	91.320 mi
Registration #12	2015-12-10	91.320 mi
Registration #13		9.77 66
Registration #14		11.777 es
Registration #15		9.77 66
Registration #16		11.777 es
Registration #17		9.77 66
Registration #18		11.777 es
Registration #19		9.77 66
Registration #20		11.777 es
Registration #21		0.074
Registration #22		0.00 44
Registration #23		
Registration #25		

More info >



## Car features

S0225	Air conditionin
S0295	
S0482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1279 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Engine number	DYPS4008262

CarCheck.co.uk page 15/15