



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Silver
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-11-10
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2023-06-03
<b>MOT pass rate</b>	85 %
<b>MOT passed</b>	17
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	29
<b>Total items failed</b>	3

<b>MOT #20</b>	2022-06-04 12:14
<b>MOT test number</b>	729163845669
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-06-03

<b>MOT #19</b>	2021-07-20 11:03
<b>MOT test number</b>	309026092966
<b>Result</b>	✓ Passed
<b>Minor</b>	Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

<b>MOT #18</b>	2020-07-30 10:20
<b>MOT test number</b>	517536093096
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2019-07-29 11:12

**MOT test number**

702387900686

**Result**

✓ Passed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Inner Drive shaft joint constant velocity boot severely deteriorated both sides (6.1.7 (g) (i))**MOT #16**

2018-07-16 12:07

**MOT test number**

130876992704

**Result**

✓ Passed

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #15**

2017-07-26 10:08

**MOT test number**

417978984351

**Result**

✓ Passed

**Advice** Front Shock absorber has a light misting of oil both sides (2.7.3)**MOT #14**

2016-07-21 10:20

**MOT test number**

671182900994

**Result**

✓ Passed

**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt both sides (2.5.C.1a)

**MOT #13** 2015-07-16 13:44**MOT test number** 987537595138**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #12** 2014-07-15 10:40**MOT test number** 606896294112**Result** ✓ Passed**MOT #11** 2013-07-25 10:40**MOT test number** 479346703245**Result** ✓ Passed**MOT #10** 2012-07-31 16:04**MOT test number** 927623612282**Result** ✓ Passed**MOT #9** 2012-07-30 09:58**MOT test number** 847152712278**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Wheel alignment should be checked**MOT #8** 2011-07-25 08:49**MOT test number** 337116201286**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)

**MOT #7** 2011-07-25 08:49**MOT test number** 336026201207**Result** ✓ Passed**MOT #6** 2010-07-23 09:01**MOT test number** 193924400260**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-07-25 07:38**MOT test number** 711736809280**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Rear Registration plate lamp not working (1.1.5c)**MOT #4** 2009-07-25 07:38**MOT test number** 490716809231**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2008-07-30 07:38
MOT test number	804582118274
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear Stop lamp not working (1.2.1b)	

MOT #2	2008-07-30 07:38
MOT test number	174502118256
Result	✓ Passed

MOT #1	2007-07-23 10:57
MOT test number	740034407245
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
10 June 2022

X

MOT

Expired:  
3 June 2023

Tax status	Expired at 10 June 2022
Days left	689 days too late
MOT expiry date	3 June 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-07-29
Last registration	2022-06-04
Complete history	<a href="#">See info</a>



Registration #1	2004-07-29	19 mi
Registration #2	2007-07-23	17.419 mi
Registration #3	2008-07-30	22.847 mi
Registration #4	2009-07-25	26.940 mi
Registration #5	2010-07-23	30.457 mi
Registration #6	2011-07-25	35.598 mi
Registration #7	2012-07-30	40.140 mi
Registration #8	2012-07-31	40.148 mi
Registration #9	2013-07-25	44.591 mi
Registration #10	2014-07-15	49.200 mi
Registration #11	2015-07-20	53.717 mi
Registration #12	2016-07-20	58.234 mi
Registration #13	2017-07-20	62.751 mi
Registration #14	2018-07-20	67.268 mi
Registration #15	2019-07-20	71.785 mi
Registration #16	2020-07-20	76.302 mi
Registration #17	2021-07-20	80.819 mi
Registration #18	2022-06-04	85.336 mi
Registration #19	2023-06-04	89.853 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Engine number	1KD1142008