



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 SW SE
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	13.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.0 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-12-24
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-12-24
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-12-28
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	18
Total items failed	10

MOT #19	2023-12-15 09:47
MOT test number	790581993964
Result	✓ Passed
Next expiry date	2024-12-28

MOT #18	2022-12-29 13:07
MOT test number	702009163811
Result	✓ Passed

MOT #17	2022-12-29 10:45
MOT test number	329123129545
Result	✗ Failed
Fail	Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16	2021-12-23 13:00
MOT test number	192149168030
Result	✓ Passed

**MOT #15** 2021-02-09 10:23**MOT test number** 193665163499**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2020-02-04 08:47**MOT test number** 371271459416**Result** ✓ Passed**MOT #13** 2019-03-27 17:09**MOT test number** 835326410325**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)

**MOT #12** 2019-03-27 09:29**MOT test number** 409501302767**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Play in steering rack inner joint(s)**MOT #11** 2017-10-24 14:51**MOT test number** 229854107426**Result** ✓ Passed**MOT #10** 2016-11-08 12:13**MOT test number** 693008941181**Result** ✓ Passed**MOT #9** 2016-11-04 12:22**MOT test number** 366675941744**Result** ✗ Failed**Fail** Brake pedal creeps down when held under pressure (3.3.B.1a)**Fail** Offside Rear brake caliper leaking (3.6.A.1)**MOT #8** 2016-03-30 09:19**MOT test number** 185193573310**Result** ✓ Passed**Advice** Nearside Front Steering arm has slight play

**MOT #7** 2015-04-01 12:06**MOT test number** 618741495018**Result** ✓ Passed**Notice** Both rear tyres cracking**Notice** Slight play in nearside front steering**MOT #6** 2014-04-07 10:30**MOT test number** 905177894084**Result** ✓ Passed**MOT #5** 2013-04-12 14:40**MOT test number** 698112803118**Result** ✓ Passed**Notice** Slight play in n/s/front steering rack arm inner bull joint**MOT #4** 2013-04-12 09:37**MOT test number** 805692803111**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Notice** Slight play in n/s/front steering rack arm inner bull joint**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #3** 2012-04-14 09:37**MOT test number** 545755402166**Result** ✓ Passed**Notice** Deep cut to offside rear tyre tread



MOT #2	2011-04-07 11:35
MOT test number	587207991079
Result	✓ Passed

MOT #1	2011-04-07 11:35
MOT test number	439877691055
Result	✗ Failed
<div>Pass with rectification</div> Nearside Headlamp aim too low (1.8)	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
28 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	HN08YBC
Plate since	2024-03-28
Current registration	HN08YBC
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-30
Last registration	2023-12-15
Complete history	See info



Registration #1	2008-05-30	26 mi
Registration #2	2011-04-07	24.735 mi
Registration #3	2012-04-14	30.891 mi
Registration #4	2013-04-12	38.112 mi
Registration #5	2013-04-12	38.112 mi
Registration #6	2014-04-07	44.103 mi
Registration #7	2015-04-01	51.595 mi
Registration #8	2016-03-30	57.442 mi
Registration #9	2016-11-04	60.090 mi
Registration #10	2016-11-08	60.090 mi
Registration #11	2017-10-24	71.630 mi
Registration #12	2018-05-29	75.277 mi
Registration #13	2018-05-29	75.277 mi
Registration #14	2018-05-29	75.277 mi
Registration #15	2018-05-29	75.277 mi
Registration #16	2018-05-29	75.277 mi
Registration #17	2018-05-29	75.277 mi
Registration #18	2018-05-29	75.277 mi
Registration #19	2018-05-29	75.277 mi
Registration #20	2018-05-29	75.277 mi
Registration #21	2018-05-29	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1762 mm
Height	1580 mm
Length	4428 mm
Wheel base	2708 mm
Kerb weight	1469 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	FX7V3305089