




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Red
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-10
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-01-31
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	59
Total items failed	8

MOT #212023-04-17 10:27

MOT test number874171914664

ResultX Failed

- AdviceBrake pipe corroded, covered in grease or other material swollen (1.1.11 (c))
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOREngine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOREmissions unable to be completed due to excessive smoke (8.2.1.2 (d))
- AdviceNearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJORExhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))
- MAJORElectronic stability control warning lamp indicates a fault (7.12 (e))
- AdviceFront Coil spring corroded both (5.3.1 (b) (i))

**MOT #20**

2023-02-15 16:31

MOT test number

647847196291

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

MOT #19

2022-02-01 13:08

MOT test number

288153089969

Result**✓ Passed**

**MOT #18**

2020-12-03 16:58

MOT test number

577735502117

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17

2020-12-02 17:19

MOT test number

888576131179

Result

✗ Failed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16**

2019-06-04 16:14

MOT test number

800867186642

Result

✓ Passed

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened Both front and rear (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15

2019-05-10 11:17

MOT test number

849665641124

Result

✗ Failed

MAJOR Speedometer clearly inoperative (7.8 (b) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MAJOR Emissions not tested excessive amount of smoke being emitted (8.2.1.2 (d))

Advice Offside Front Nail in tyre

MAJOR Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #14

2018-05-17 15:33

MOT test number

260810408124

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #13** 2018-05-17 09:11**MOT test number** 819657311357**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image kick up to the offside (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Central Stop lamp not working (1.2.1b)**Advice** Offside Rear Nail in tyre**MOT #12** 2017-05-23 07:26**MOT test number** 434292666211**Result** ✓ Passed**MOT #11** 2016-04-04 15:19**MOT test number** 711983886142**Result** ✓ Passed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #10** 2016-04-04 11:33**MOT test number** 865851335204**Result** ✗ Failed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #9** 2015-02-19 13:48**MOT test number** 596470155091**Result** ✓ Passed

**MOT #8** 2014-05-01 13:26**MOT test number** 955511124177**Result** ✓ Passed**MOT #7** 2014-04-30 15:48**MOT test number** 799150124198**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #6** 2014-01-28 12:21**MOT test number** 875788724073**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-01-31 09:40**MOT test number** 885091233054**Result** ✓ Passed**Notice** N/s front wheel is stiff when rotated by hand**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front discs are worn

**MOT #4** 2013-01-31 09:40**MOT test number** 269481633053**Result** ✗ Failed**Notice** N/s front wheel is stiff when rotated by hand**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Front discs are worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-03-03 12:16**MOT test number** 189773262023**Result** ✓ Passed**MOT #2** 2011-01-28 11:26**MOT test number** 109668121422**Result** ✓ Passed**MOT #1** 2011-01-25 13:00**MOT test number** 968715521011**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✕
Untaxed

Tax expired:
1 May 2023

✕
MOT

Expired:
31 January 2023

Tax status	Expired at 1 May 2023
Days left	364 days too late
MOT expiry date	31 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 MM57CFU
Plate since	2019-06-29
Current registration	 MM57CFU
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-02-22
Last registration	2023-04-17
Complete history	See info



Registration #1	2008-02-22	9 mi
Registration #2	2011-01-25	28.474 mi
Registration #3	2011-01-28	285.892 mi
Registration #4	2012-03-03	40.948 mi
Registration #5	2013-01-31	47.386 mi
Registration #6	2014-01-28	53.655 mi
Registration #7	2014-04-30	54.477 mi
Registration #8	2014-05-01	54.477 mi
Registration #9	2015-02-19	59.708 mi
Registration #10	2016-04-04	65.030 mi
Registration #11	2016-04-04	65.030 mi
Registration #12	2016-05-20	65.030 mi
Registration #13	2016-05-20	65.030 mi
Registration #14	2016-05-20	65.030 mi
Registration #15	2016-05-20	65.030 mi
Registration #16	2016-05-20	65.030 mi
Registration #17	2016-05-20	65.030 mi
Registration #18	2016-05-20	65.030 mi
Registration #19	2016-05-20	65.030 mi
Registration #20	2016-05-20	65.030 mi
Registration #21	2016-05-20	65.030 mi
Registration #22	2016-05-20	65.030 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

BFS 071176