



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA 16V CLUB
Colour	Silver
Year of manufacture	2002
Top speed	96 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.199 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	49.6 mpg
Consumption combined	43.5 mpg
CO2 emission	156 g/km
CO2 label	G








Internet history

Entry 1

Date	2021-06-04
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	79 %
MOT passed	19
Failed MOT tests	5
Total advice items	35
Total items failed	11

MOT #24	2023-05-23 08:21
MOT test number	733334772904
Result	✓ Passed
Next expiry date	2024-05-31

MOT #23	2022-05-24 08:16
MOT test number	292864690431
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #22	2021-06-01 12:53
MOT test number	434021155106
Result	✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing offside and nearside (5.2.3 (d) (ii))

MOT #21	2021-06-01 12:53
MOT test number	429685767565
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing offside and nearside (5.2.3 (d) (ii))
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #20** 2020-07-15 08:09**MOT test number** 491699038461**Result** ✓ Passed**MOT #19** 2019-04-04 14:00**MOT test number** 793311287427**Result** ✓ Passed**MOT #18** 2018-04-19 15:47**MOT test number** 948551587693**Result** ✓ Passed**MOT #17** 2018-04-19 07:49**MOT test number** 566531245740**Result** ✗ Failed**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**MOT #16** 2017-04-10 16:36**MOT test number** 998149839509**Result** ✓ Passed**Advice** Rear tyres cracking up in deep part of tread**Advice** Wheel-trims fitted - retainers not checked**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Front section of exhaust corroding**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside front wiper deteriorating - splitting

**MOT #15**

2017-04-10 10:15

MOT test number

410409234313

Result

✗ Failed

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)

Advice

Nearside front wiper deteriorating - splitting

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively split (8.2.2)

Advice

Front section of exhaust corroding

Advice

Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice

Wheel-trims fitted - retainers not checked

Fail

Rear Registration plate lamp not working (1.1.C.1d)

Advice

Coolant level low

Advice

Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice

Rear tyres cracking up in deep part of tread

MOT #14

2016-04-25 08:15

MOT test number

341607330890

Result

✓ Passed

Advice

Coolant level low

Advice

Front section of exhaust corroding

Advice

Macpherson strut has slight movement at the upper attachment both front (2.5.A.1c)

Advice

Wheel-trims fitted - retainers not checked

MOT #13

2015-06-30 09:22

MOT test number

179601285126

Result

✓ Passed

Notice

Centre exhaust baffles getting weak

**MOT #12** 2014-07-15 09:23**MOT test number** 979576194142**Result** ✓ Passed

- Notice** Coolant leak from radiator
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Notice** Gearbox oil leak
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #11 2013-07-18 16:48**MOT test number** 275189793177**Result** ✓ Passed

- Notice** Offside front tyre badly worn on inner edge
- Notice** Nearside front tyre worn on inner edge
- Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

MOT #10 2013-07-18 09:43**MOT test number** 629949193118**Result** ✗ Failed

- Fail** Rear registration plate missing (6.3.1a)
- Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Offside front tyre badly worn on inner edge
- Fail** Front registration plate missing (6.3.1a)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Notice** Nearside front tyre worn on inner edge
- Notice** Coolant level very low



MOT #9	2012-07-12 12:23
---------------	------------------

MOT test number	837764792111
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2011-07-08 14:17
---------------	------------------

MOT test number	887789481138
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2010-07-12 11:10
---------------	------------------

MOT test number	242343490106
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2009-06-30 08:46
---------------	------------------

MOT test number	533401489162
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
--------------------------------	--

Pass with rectification	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
--------------------------------	---

MOT #5	2009-06-30 08:46
---------------	------------------

MOT test number	771131189163
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2008-07-23 12:31
---------------	------------------

MOT test number	700655208281
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2007-07-11 10:52
---------------	------------------

MOT test number	700272397124
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #2	2006-07-22 11:33
MOT test number	431863206270
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2006-01-31 09:53
MOT test number	330281736003
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2019-09-29
Current registration	 VAUXH
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-10-04
Last registration	2023-05-23
Complete history	See info



Registration #1	2002-10-04	7 mi
Registration #2	2006-01-31	12.266 mi
Registration #3	2006-07-22	12.860 mi
Registration #4	2007-07-11	17.783 mi
Registration #5	2008-07-23	22.876 mi
Registration #6	2009-06-30	28.349 mi
Registration #7	2009-06-30	288.349 mi
Registration #8	2010-07-12	31.747 mi
Registration #9	2011-07-08	38.105 mi
Registration #10	2012-07-12	44.082 mi
Registration #11	2013-07-18	49.738 mi
Registration #12	2013-07-18	49.738 mi
Registration #13	2014-07-15	56.638 mi
Registration #14	2015-05-20	56.557 mi
Registration #15	2015-05-20	56.557 mi
Registration #16	2015-05-20	56.557 mi
Registration #17	2015-05-20	56.557 mi
Registration #18	2015-05-20	56.557 mi
Registration #19	2015-05-20	56.557 mi
Registration #20	2015-05-20	56.557 mi
Registration #21	2015-05-20	56.557 mi
Registration #22	2015-05-20	56.557 mi
Registration #23	2015-05-20	56.557 mi
Registration #24	2015-05-20	56.557 mi
Registration #25	2015-05-20	56.557 mi
Registration #26	2015-05-20	56.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1660 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	960 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	19X53713