





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 T-GDI PREMIUM SE
Colour	White
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-10-24	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-04
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	21
Total items failed	0

MOT #5		2023-11-02 09:26
MOT test	number	566057218291
Result		✓ Passed
Next expi	ry date	2024-11-04
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened ALL BRAKE	E DISC'S (1.1.14 (a) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Steering column universal joint has slight wear or play (2.2.2 (c))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #4		2022-11-03 13:05
MOT test	number	944144681090
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 195/55R16 DOT 4110	6 (5.2.3 (d) (ii))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 195/55R16 (5.2.3 (e))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 195/55R16 DOT 4116	(5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 195/55R16 (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2021-11-05 17:13
MOT test number	590479545365
Result	✓ Passed
MOT #2	2021-01-22 09:17
MOT test number	297235137579
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2020-01-24 11:02

MOT test number 372822141031

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Tax status	Valid until 1 November
Days left	185
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



HG66AWY report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\cap	ner	hi	~+~	-
UΝ	mer.		รเบ	H V

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET CONTRACTOR CONT	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	JK UK
Flate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-01-31
Last registration	2023-11-02
Complete history	See info



Registration #1	2017-01-31	20 mi
Registration #2	2020-01-24	9.865 mi
Registration #3	2021-01-22	12.166 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1218 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number G3LCGP038338