





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	Black
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2022-02-09

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-02-08

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2025-02-22
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #9	2024-02-09 09:24
MOT test number	841278079718
Result	✓ Passed
Next expiry date	2025-02-22

MOT #8	2023-02-10 16:09
MOT test number	151966658630
Result	✓ Passed

MOT #7		2022-02-23 14:56
MOT test	number	765011941352
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2	2021-06-12 09:38
MOT test i	number	957733030669
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #5 2020-06-13 12:56

MOT test number 233975222962

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #4 2019-06-15 14:03

MOT test number 766843170954

Result

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2018-06-17 15:26

MOT test number 217932469900

Result ✓ Passed

MOT #2 2017-12-05 12:47

MOT test number 733685238065

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2017-01-17 12:47

MOT test number 404711095289

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

LS14FSN

report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

mber of plates

-

See in this check if this VOLKSWAGEN had different number plates.

NE CONTRACTOR OF THE CONTRACTO

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-08
Last registration	2024-02-09
Complete history	See info



Registration #1	2014-04-08	22 mi
Registration #2	2017-01-17	25.706 mi
Registration #3	2017-12-05	35.416 mi
Registration #4	2018-06-17	38.678 mi
Registration #5	2019-06-15	42.646 mi
Registration #6	2020-06-13	48.679 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
CarChack co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CFFBJ33731