





General information

Make	CITROEN	
Model	C4 GRAND PURETECH FLAIR S/S	
Colour	Grey	
Year of manufacture	2018	
Top speed	125 mph	
0 - 60 mph	9.8 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	129 BHP	
Max. torque	230 Nm at 1.750 rpm	
Engine capacity	1.200 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	46.3 mpg	
Consumption extra urban	65.7 mpg	
Consumption combined	56.5 mpg	
CO2 emission	118 g/km	
CO2 label	С	







Internet history

Entry 2	
Date	2022-03-26
Pictures	12
Listing price	View report









source: cargurus.co.uk

Entry 1			
Date	2022-01-28		
Pictures	28		
Listing price	View report		



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-12
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	23
Total items failed	0

MOT #5	2023-05-09 08:51
MOT test number	192585543444
Result	🗸 Passed
Next expiry date	2024-05-12
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #42022-05-13 16:09MOT test number921312647658ResultPassedAdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))AdviceNearside Front Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))AdviceNearside Front Inner Road wheel slightly distorted wheel rim (5.2.2 (c) (i))



MOT #3		2022-05-13 15:57
MOT test	number	282953521670
Result		🗙 Failed
Advice	Nearside Front Inner Road wheel slightly distorted wheel rim (5.2.2 (c) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))	
MAJOR cords side	Nearside Rear Inner Tyre has a cut in excess of the requirements deep enoug wall (5.2.3 (d) (i))	h to reach the ply or
Advice	Nearside Front Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))	

MOT #2		2021-10-29 16:36
MOT test	number	701416291142
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	



MOT #1	2021-1	0-27 14:38
MOT test	number 747	978394831
Result		🗙 Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
DANGER	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))



Tax & MOT check

✓ Taxed Tax due: 1 May 2025	MOT Expires: 12 May 2024
Tax status	Valid until 1 May
Days left	367
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



CE68BTF report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-10-25
Last registration	2023-05-09
Complete history	See info



Registration #1	2018-10-25	11 mi
Registration #2	2021-10-27	23.401 mi
Registration #3	2021-10-29	23.406 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		T1.777 esi





Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1826 mm
Height	1644 mm
Length	4602 mm
Wheel base	2840 mm
Kerb weight	1320 kg
Max. allowed weight	2095 kg
Additional information	
Additional information Fuel tank capacity	55 l
	55 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5