





report date: 2024-03-28

General information

Make	FIAT
Model	SCUDO PANORAMA FAMILY MULTIJET
Colour	Grey
Year of manufacture	2013
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	44.8 mpg
Consumption combined	40.4 mpg
CO2 emission	183 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-28

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



WR13WUX
report date: 2024-03-28

MOT history

MOT expiry date	2025-03-20
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	22
Total items failed	0

MOT #11		2024-03-20 09:46
MOT test	number	260858995644
Result		✓ Passed
Next expi	ry date	2025-03-20
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin Nearside and Offside (1.1.13 (a) (ii))		
Advice	Front Brake pad(s) wearing thin Nearside and Offside (1.1.13 (a) (ii))	

MOT #10	2023-03-21 12:56
MOT test number	249609554509
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #9		2023-03-21 12:12
MOT test	number	582782907686
Result		🗙 Failed
MAJOR Advice	Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b)) Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2022-06-28 10:16

MOT test number 352829402113

Result ✓ Passed

Advice

Rear Tyre worn close to legal limit/worn on edge Nearside and Offside (5.2.3 (e))

MOT #7 2022-06-17 11:19

MOT test number 503450965959

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Registration plate does not conform to the specified requirements (0.1 (d))

MAJOR Power steering fluid reservoir empty (2.1.5 (b) (ii))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6 2021-06-17 15:57

MOT test number 969522529230

Result ✓ Passed

MOT #5 2020-06-15 11:03

MOT test number 694574343223

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #4 2019-07-26 11:38

MOT test number 914536193425

Result \(\sqrt{Passed} \)

Advice Front and rear brake disc,s lipped

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2019-07-23 16:17

MOT test number 341437134578

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Front Road wheel fixing missing both (5.2.1 (a) (i))

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front and rear brake disc,s lipped

MAJOR Headlamp aim too high both (4.1.2 (a))

MAJOR Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #2 2018-07-19 11:24

MOT test number 826907353849

Result

✓ Passed

MOT #1 2017-01-30 16:54

MOT test number 341910652485

Result
✓ Passed

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

For how long did the current and previous owner(s) have this FIAT? How many owners die Check it in the premium report and see all owner registrations. Download the full report I		e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12





report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-12
Last registration	2024-03-20
Complete history	See info



Registration #1	2013-06-12	12 mi
Registration #2	2017-01-30	50.811 mi
Registration #3	2018-07-19	67.033 mi
Registration #4	2019-07-23	80.540 mi
Registration #5	2019-07-26	80.553 mi
Registration #6	2020-06-15	90.453 mi
Registration #7	2021-06-17	105.594 mi
Registration #8		11.777 es
Registration #9		9.77 es
Registration #10		11.777 es
Registration #11		91.777 ms
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1880 mm
Length	5135 mm
Wheel base	3120 mm
Kerb weight	1911 kg
Max. allowed weight	2930 kg

Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	8	page 12/12

Number of axles 2

Engine number 4059726