



MD55HAM

report date: 2024-03-29

General information

Make	MAZDA
Model	5 D SPORT NAV
Colour	White
Year of manufacture	2012
Top speed	111 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-01-20
Pictures	30
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-18
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	29
Total items failed	6

MOT #16	2024-02-15 17:14
MOT test number	483632674834
Result	✓ Passed
Next expiry date	2025-02-18
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2024-02-14 11:03
MOT test number	494498055051
Result	✗ Failed
DANGEROUS	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2023-02-16 15:36**MOT test number** 347496457128**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #13** 2023-02-13 10:50**MOT test number** 758973947791**Result** ✗ Failed**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #12** 2022-02-19 12:27**MOT test number** 123228026932**Result** ✓ Passed**MOT #11** 2022-02-16 13:39**MOT test number** 763466644651**Result** ✗ Failed**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2021-01-27 14:07**MOT test number** 584538055106**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #9	2020-01-22 14:34
MOT test number	529699873183
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt Both rear.

MOT #8	2020-01-22 11:02
MOT test number	598328134449
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, but not excessively Both. (1.1.14 (a) (i))
Advice	Rear Child Seat fitted not allowing full inspection of adult belt Both rear.
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #7	2019-01-18 11:13
MOT test number	506112728754
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6	2018-01-27 11:58
MOT test number	768101097713
Result	✓ Passed

**MOT #5** 2018-01-27 09:00**MOT test number** 143893874951**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Front brake disc in such a condition that it is seriously weakened inner faces heavily corroded (3.5.1i)

MOT #4 2017-10-27 14:45**MOT test number** 329989163253**Result** ✓ Passed**MOT #3** 2016-02-23 16:15**MOT test number** 651626182423**Result** ✓ Passed

- Advice** Surface corrosion to front brake discs
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre exhaust heat tray insecure

MOT #2 2016-02-23 14:02**MOT test number** 550684760975**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Surface corrosion to front brake discs
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Centre exhaust heat tray insecure
- Fail** Front position lamp(s) not working nearside and offside (1.1.A.3b)



MOT #1	2015-02-24 13:09
MOT test number	828545855037
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-30
Last registration	2024-02-15
Complete history	See info



Registration #1	2012-03-30	28 mi
Registration #2	2015-02-24	23.072 mi
Registration #3	2016-02-23	29.469 mi
Registration #4	2016-02-23	29.469 mi
Registration #5	2017-10-27	32.182 mi
Registration #6	2018-01-27	33.612 mi
Registration #7	2018-01-27	33.614 mi
Registration #8	2019-01-18	37.624 mi
Registration #9	2020-01-22	45.408 mi
Registration #10	2020-01-22	45.408 mi
Registration #11	2020-01-22	45.408 mi
Registration #12	2020-01-22	45.408 mi
Registration #13	2020-01-22	45.408 mi
Registration #14	2020-01-22	45.408 mi
Registration #15	2020-01-22	45.408 mi
Registration #16	2020-01-22	45.408 mi
Registration #17	2020-01-22	45.408 mi
Registration #18	2020-01-22	45.408 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 347214