





report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE S MEDIANAV ENERGY TCE S/S
Colour	Black
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history


Entry 1

Date 2021-05-25

Pictures 51

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-07
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	11
Total items failed	14

MOT #13		2023-06-29 14:04
MOT test	number	738750508625
Result		✓ Passed
Next expi	ry date	2024-07-07
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front		
bush (5.3.4 (a) (i))		

MOT #12	2023-06-29 10:07
MOT test number	918630110232
Result	X Failed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #11		2022-06-28 12:48
MOT test	number	667601481065
Result		✓ Passed
Advice	Advice tracking	
Advice	All suspension springs are corrroded	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #10 2022-06-28 08:22 **MOT** test number 364590832019 Result × Failed Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice All suspension springs are corrroded Fail Front Service brake excessively fluctuating (1.2.1 (e)) Fail Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Advice Advice tracking

MOT #9	2021-06-08 07:39
MOT test number	775363698079
Result	✓ Passed

MOT #8	2021-06-05 11:28
MOT test number	165177683037
Result	★ Failed
Fail Offside Front Brake pipe excessively co	prroded at the flexi (1.1.11 (c))
Fail Nearside Front Coil spring fractured or	broken (5.3.1 (b) (i))

MOT #7	2020-07-08 13:28
MOT test number	319949012475
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #6 2020-07-08 13:28 MOT test number 376848342883

Result X Failed

Pass with rectification

Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #5 2019-06-27 14:12

MOT test number 747058457678

Advice Both rear tyres cracking but no visible cords

MOT #4 2018-06-21 14:45

MOT test number 371256382504

Result ✓ Passed

MOT #3 2018-06-20 12:26

MOT test number 569570217912

Result × Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #2 2017-06-16 15:45

MOT test number 213636652291

Result
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

673670105160

Result

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Brake pedal anti-slip provision worn smooth split (3.3.A.1b)

Fail Offside Windscreen wiper does not clear the windscreen effectively split (8.2.2)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

\sim	
Owner	nictory
CVVIICI	IIISLUIV
~	,

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full		JLT

	More info >	
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	NE UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-05-14
Last registration	2023-06-29
Complete history	See info



Registration #1	2014-05-14	23 mi
Registration #2	2017-05-31	19.820 mi
Registration #3	2017-06-16	19.821 mi
Registration #4	2018-06-20	20.936 mi
Registration #5	2018-06-21	20.936 mi
Registration #6	2019-06-27	36.856 mi
Registration #7	2020-07-08	40.007 mi
Registration #8	2020-07-08	40.007 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11,117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1945 mm
Height	1448 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Engine number

U208929