





report date: 2024-03-28

## General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Red
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-01-29

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2024-10-25
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #13		2023-10-17 15:17
MOT test	number	602274455474
Result		<b>✓</b> Passed
Next expi	ry date	2024-10-25
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #12	2023-10-17 10:19	
MOT test number	269400273470	
Result	<b>★</b> Failed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm and HEAVILY WORN ON INNER EDGE (5.2.3 (e))		
Advice Offside Front Upper Macphers (5.3.4 (a) (i))	son strut pin or bush worn but not resulting in excessive movement	
<b>DANGEROUS</b> Offside Front Tyre trea	nd depth below requirements of 1.6mm (5.2.3 (e))	
<b>DANGEROUS</b> Nearside Rear Tyre has	s ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))		

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11

MOT test number

Result

Advice Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10 2021-10-26 11:22 **MOT** test number 507793394780 Result ✓ Passed **MOT** #9 2020-10-15 10:10 **MOT** test number 360010043690 ✓ Passed Result **MOT** #8 2020-10-07 07:27 180758303658 **MOT** test number Result × Failed **DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge 2/3mm and bold inner edge (5.2.3 (e))

Advice

Nearside mirror glass damaged

MOT #6

MOT test number

Passed

Advice Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

187930913074

Result

Advice Offside Front tyre worn inner edge

 MOT #4
 2015-08-24 12:06

 MOT test number
 651525190992

 Result
 ✓ Passed

 MOT #3
 2014-09-04 10:25

 MOT test number
 476857444227

MOT #2 2013-08-29 10:03

**MOT test number** 917671743276

Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #1 2012-08-21 10:20
MOT test number 866704632268
Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	25 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

റ	wr	er	hi	cti	nr.

e mier metery	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
**************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NE NE
Flate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-02
Last registration	2023-10-17
Complete history	See info



Registration #1	2009-09-02	10 mi
Registration #2	2012-08-21	6.718 mi
Registration #3	2013-08-29	8.117 mi
Registration #4	2014-09-04	11.791 mi
Registration #5	2015-08-24	15.070 mi
Registration #6	2016-08-18	17.117 mi
Registration #7	2017-08-16	18.185 mi
Registration #8	2018-09-11	21.505 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982488870

CarCheck.co.uk page 12/12