




report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 8V DYNAMIC
Colour	Grey
Year of manufacture	2006
Top speed	92 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-06
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	28
Total items failed	3

MOT #19	2023-10-19 13:53
MOT test number	630859998126
Result	✓ Passed
Next expiry date	2024-10-25
Advice	EXHAUST REAR HEATSHIELD INSECURE
Advice	Oil leak, but not excessive SLIGHT ENGINE OIL LEAK (8.4.1 (a) (i))

MOT #18	2022-10-24 15:47
MOT test number	325405924549
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Surface corrosion
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2022-10-19 12:48**MOT test number** 999573258627**Result** ✗ Failed

- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Surface corrosion
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2021-10-26 09:27**MOT test number** 827261652937**Result** ✓ Passed**MOT #15** 2021-10-16 13:48**MOT test number** 396133207930**Result** ✗ Failed

- Fail** Oil leaking excessively from engine sump porous (8.4.1 (a) (i))

MOT #14 2020-09-30 10:29**MOT test number** 271140217223**Result** ✓ Passed**MOT #13** 2019-09-17 15:52**MOT test number** 802696458752**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2018-09-15 09:46

MOT test number

943387265412

Result

✓ Passed

Advice O/s/r tyre wearing on edges**MOT #11**

2017-09-04 08:01

MOT test number

222647736111

Result

✓ Passed

Advice N/s/f tyre wearing on outside edge slightly**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10**

2016-09-17 09:34

MOT test number

566910255456

Result

✓ Passed

Advice O/s/r shock absorber upper bush deteriorated**Advice** Oil leak at sump**Advice** N/s/r shock absorber upper bush deteriorated**MOT #9**

2015-09-12 07:55

MOT test number

170131711439

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front exhaust flexi slightly deteriorated**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2014-09-06 09:17**MOT test number** 486439044204**Result** ✓ Passed**Notice** Both rear tyres slightly perished**MOT #7** 2013-09-04 10:13**MOT test number** 886347143244**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s/r tyre cracked but no cords showing and o/s/r starting to crack on sidewall**MOT #6** 2012-09-13 08:47**MOT test number** 975217752232**Result** ✓ Passed**MOT #5** 2012-09-07 12:55**MOT test number** 477751952292**Result** ✗ Failed**Fail** Power steering component(s) leaking (2.3.3b)**MOT #4** 2011-09-10 09:23**MOT test number** 588533051288**Result** ✓ Passed**MOT #3** 2011-04-06 14:48**MOT test number** 339036491055**Result** ✓ Passed



MOT #2	2010-04-30 14:17
MOT test number	124850720171
Result	✓ Passed
MOT #1	2009-06-12 13:55
MOT test number	254673569467
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-26
Last registration	2023-10-19
Complete history	See info



Registration #1	2006-07-26	11 mi
Registration #2	2009-06-12	8.553 mi
Registration #3	2010-04-30	10.894 mi
Registration #4	2011-04-06	14.699 mi
Registration #5	2011-09-10	17.154 mi
Registration #6	2012-09-07	25.003 mi
Registration #7	2012-09-13	25.003 mi
Registration #8	2013-09-04	33.229 mi
Registration #9	2014-09-06	42.265 mi
Registration #10	2015-09-12	52.776 mi
Registration #11	2016-09-17	63.685 mi
Registration #12	2017-09-20	75.277 mi
Registration #13	2018-09-20	86.869 mi
Registration #14	2019-09-20	98.461 mi
Registration #15	2020-09-20	110.053 mi
Registration #16	2021-09-20	121.645 mi
Registration #17	2022-09-20	133.237 mi
Registration #18	2023-09-20	144.829 mi
Registration #19	2024-03-28	156.421 mi
Registration #20		
Registration #21		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1818 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3449306