





report date: 2024-03-28

### General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 L LWB P/V 90
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-10-09

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-12-29
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	11
Total items failed	9

MOT #21	2023-12-19 16:52
MOT test number	317578090417
Result	<b>✓</b> Passed
Next expiry date	2024-12-29

MOT #20	2023-12-15 16:09
MOT test number	297800615451

Result × Failed

**Fail** Nearside Rear Outer Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))

MOT #19	2022-12-30 12:51
MOT test number	691235096649
Result	✓ Passed

MOT #	<b>18</b> 2022-12-29 16:4	6
MOT te	est number 89966951004	.5
Result	<b>▼</b> Faile	d
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))		
Fail	Rear fog lamp not working (4.5.1 (a) (ii))	
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #17 2021-11-11 18:19

**MOT test number** 275727853482

MOT #16 2021-06-21 12:20

**MOT test number** 535044351695

**Result** ✓ Passed

**MOT #15** 2019-06-29 09:12

**MOT test number** 685437977165

Result \( \sqrt{Passed} \)

Minor Headlamp lens slightly defective (4.1.1 (b) (i))

Minor Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

**Advice** Wiper blades on limit

**MOT #14** 2018-06-09 07:12

MOT test number 461963967935

Result \( \sqrt{Passed} \)

**MOT #13** 2018-06-09 07:12

**MOT test number** 872960655310

Result X Failed

**Pass with rectification** Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

MOT #12 2017-06-19 10:26

MOT test number 493234259421

CarCheck.co.uk page 4/13



**MOT #8** 

**GF070FP** 

report date: 2024-03-28

2014-07-14 13:36

MOT #11

MOT test number

638853414947

Result

Advice Nearside Front Tyre perished

Advice Offside Front Tyre perished

MOT #10

MOT test number

677311105201

Result

Notice Exhaust back box corroded

Notice Oil leak

MOT test number

Result

Notice Oil leak

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Notice Exhaust back box corroded

MOT test number

Result

MOT #7

2013-07-23 13:48

MOT test number

249834303231

Result

Notice Oil leak

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6 2012-07-17 12:43

**MOT test number** 597009792174

**Result** 
✓ Passed

MOT #5 2012-07-17 09:47

**MOT test number** 385449692107

Result X Failed

**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)

MOT #4 2011-07-22 16:22

**MOT test number** 566573901277

Result \rightarrow Passed

MOT #3 2011-07-22 16:22

**MOT test number** 928343401219

**Result** X Failed

**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #2 2010-12-24 10:14

**MOT test number** 253058950391

**Result** ✓ Passed

**MOT #1** 2010-05-17 17:41

MOT test number 353717030120

**Result** ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28





Days left 187

MOT expiry date 29 December 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners di Check it in the premium report and see all owner registrations. Download the full report $\underline{h}$	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-20
Last registration	2023-12-19
Complete history	See info



Registration #1	2007-06-20	9 mi
Registration #2	2010-05-17	39.694 mi
Registration #3	2010-12-24	45.490 mi
Registration #4	2011-07-22	55.726 mi
Registration #5	2012-07-17	61.473 mi
Registration #6	2012-07-17	61.473 mi
Registration #7	2013-07-23	76.186 mi
Registration #8	2014-07-14	79.742 mi
Registration #9	2015-07-20	82.606 mi
Registration #10	2015-07-20	82.606 mi
Registration #11	2016-07-15	84.546 mi
Registration #12		77,777 46
Registration #13		11.177 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		77.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

# Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Kerb weight	1399 kg
Max. allowed weight	2340 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	7T48963

CarCheck.co.uk page 13/13