






report date: 2024-03-29

General information

| Make | SUZUKI |
|---------------------|----------------|
| Model | VITARA SZ-T |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 112 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 156 Nm at 4.400 rpm |
| Engine capacity | 1.586 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-04

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

| MOT history | M | OT | history |
|-------------|---|----|---------|
|-------------|---|----|---------|

| MOT expiry date | 2025-02-27 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 6 |
| Failed MOT tests | 0 |
| Total advice items | 4 |
| Total items failed | 0 |

| MOT #6 | | 2024-01-31 15:25 |
|---|---|------------------|
| MOT test | number | 936994966003 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-02-27 |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #5 | 2023-02-09 09:34 |
|-----------------|------------------|
| MOT test number | 242275222952 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2022-02-28 10:53 |
| MOT test number | 484582630390 |
| Result | ✓ Passed |
| | |

| MOT #3 | 2021-03-29 10:14 |
|-----------------|------------------|
| MOT test number | 609326278865 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



NA65OHW

report date: 2024-03-29

| MOT #2 | | 2020-03-06 15:56 |
|--------------------|--|------------------|
| MOT test numb | er | 685588064509 |
| Result | | ✓ Passed |
| Advice Near | side Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice Cent | ral Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #1 | 2019-03-07 09:37 |
|-----------------|------------------|
| MOT test number | 131215837212 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 366 |
| MOT expiry date | 27 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| _ | |
|--------|-----------|
| Owner | history |
| OWITCE | ilistoi y |

| For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | | |
|--|-------------|---|
| | | |
| manage of the same | | |
| *************************************** | | |
| *************************************** | | |
| ********* | | |
| *************************************** | | |
| *************************************** | | |
| | More info > | |
| Plate changes | | |
| See in this check if this SUZUKI had different number plates. | | |
| Number of plates | | 9 |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info > | |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-02-12 |
| Last registration | 2024-01-31 |
| Complete history | See info |



| Registration #1 | 2016-02-12 | 11 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-03-07 | 23.600 mi |
| Registration #3 | 2020-03-06 | 24.701 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 76% |
| Safety systems | 75% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1775 mm |
|---------------------|---------|
| Height | 1610 mm |
| Length | 4175 mm |
| Wheel base | 2500 mm |
| Kerb weight | 1150 kg |
| Max. allowed weight | 1730 kg |

Additional information

| Fuel tank capacity | 47 |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | M16A-2060332 |

CarCheck.co.uk page 11/11