





report date: 2024-03-28

General information

Make	PEUGEOT
Model	PARTNER HDI ORIGIN 800
Colour	White
Year of manufacture	-
Top speed	93 mph
0 - 60 mph	17.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	170 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg



CarCheck.co.uk page 1/11



MOT history

Advice

MOT #14 2021-07-05 09:47 211787747178 **MOT** test number Result Passed **Next expiry date** 2022-07-29 Minor Horn not working properly (7.7 (a) (i)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT test number

Result

Advice

Power steering component has slight seepage from a component steering rack (2.1.5 (a))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #12
 2019-07-27 09:17

 MOT test number
 532099148317

 Result
 ✓ Passed

 Advice
 Gears stiff

MOT #11

MOT test number

Failed

Advice Gears stiff

Pass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 2/11



MOT #10 2018-07-30 10:53

MOT test number 612131250997

Result ✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material all 4 (1.1.11 (c))

Advice Injector seals leaking

Advice Gears stiff

Advice Nearside mirror broken

MOT #9 2018-07-27 13:59

MOT test number 176167883728

Result X Failed

Fail Windscreen washer not working (3.5 (a))

Advice Nearside mirror broken

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Injector seals leaking

Advice Rear Brake pipe corroded, covered in grease or other material all 4 (1.1.11 (c))

Advice Gears stiff

MOT #8 2017-07-26 13:49

MOT test number 106037815133

Result

Passed

Advice Under trays lose and hanging down

CarCheck.co.uk page 3/11



MOT #7 2016-07-29 08:38

MOT test number 409745163908

Result ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2015-02-21 09:24

MOT test number 535262555095

Result ✓ Passed

MOT #5 2014-03-10 15:14

MOT test number 349129264068

Result \rightarrow Passed

Notice Cover missing from n/s door mirror

Notice O/s/f tyre wearing on inner edge

MOT #4 2014-03-10 10:09

MOT test number 416159964061

Result X Failed

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Notice O/s/f tyre wearing on inner edge

MOT #3 2013-02-22 16:45

MOT test number 188523753026

Result
✓ Passed

Notice Rear exhaust box deteriorated

CarCheck.co.uk page 4/11



MOT #2 2013-02-16 10:09

MOT test number 147817843090

Result

× Failed

Fail

Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

Notice

Rear exhaust box deteriorated

MOT #1 2012-02-29 16:16

MOT test number 547510662046

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owr	200	oict	001
T DVVI	161 1	1151	\mathbf{o}
		1136	OI y

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	SK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-01-31
Last registration	2021-07-05
Complete history	See info



Registration #1	2009-01-31	17 mi
Registration #2	2012-02-29	50.140 mi
Registration #3	2013-02-16	57.806 mi
Registration #4	2013-02-22	57.806 mi
Registration #5	2014-03-10	63.985 mi
Registration #6	2014-03-10	63.985 mi
Registration #7	2015-02-21	69.477 mi
Registration #8	2016-07-29	78.642 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
50569	

Dimensions & weight

Width	1960 mm
Height	1819 mm
Length	4137 mm
Kerb weight	1130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	JBBV0000849

CarCheck.co.uk page 11/11