



HYUNDAI




report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | HYUNDAI        |
| Model               | GETZ CRTD GSI  |
| Colour              | Blue           |
| Year of manufacture | 2004           |
| Top speed           | 106 mph        |
| 0 - 60 mph          | 16.5 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 80 BHP              |
| Max. torque             | 191 Nm at 2.000 rpm |
| Engine capacity         | 1.493 cc            |
| Cylinders               | 3                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.8 mpg            |
| Consumption extra urban | 70.6 mpg            |
| Consumption combined    | 58.9 mpg            |
| CO2 emission            | 127 g/km            |
| CO2 label               | D                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-08                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2024-04-12 |
| <b>MOT pass rate</b>      | 80 %       |
| <b>MOT passed</b>         | 12         |
| <b>Failed MOT tests</b>   | 3          |
| <b>Total advice items</b> | 31         |
| <b>Total items failed</b> | 9          |

**MOT #15** 2023-04-13 17:13**MOT test number** 943472830040**Result** Passed**Next expiry date** 2024-04-12

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside bottom sill slight corrosion
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
- Minor** Front Window damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside bottom sill slight corroded
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14** 2022-04-07 12:56**MOT test number** 669756920688**Result** Passed

**MOT #13**

2021-06-19 15:45

**MOT test number**

171126530679

**Result**

✓ Passed

- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Service brake fluctuating, but not excessively both (1.2.1 (e))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2018-12-19 15:41

**MOT test number**

898655210402

**Result**

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #11**

2014-09-11 12:07

**MOT test number**

507574354248

**Result**

✓ Passed

**MOT #10**

2013-09-20 10:00

**MOT test number**

197663563291

**Result**

✓ Passed

**MOT #9** 2012-09-29 11:35**MOT test number** 745053672258**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2012-09-29 11:35**MOT test number** 296873472215**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2011-09-30 10:24**MOT test number** 136683671270**Result** ✓ Passed

**MOT #6** 2011-09-30 10:24**MOT test number** 988793571247**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2010-09-29 11:32**MOT test number** 973712170258**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-09-29 10:07**MOT test number** 170372970255**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2009-09-30 11:07**MOT test number** 271693379245**Result** ✓ Passed



|                                                                                |                  |
|--------------------------------------------------------------------------------|------------------|
| MOT #2                                                                         | 2007-09-11 15:11 |
| MOT test number                                                                | 314204557236     |
| Result                                                                         | ✓ Passed         |
| <div>Notice Child seat fitted not allowing full inspection of adult belt</div> |                  |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2006-09-12 15:23 |
| MOT test number | 251395756265     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 September 2024

✗  
**MOT**  
  
Expired:  
12 April 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Valid until 1 September         |
| Days left        | 125                             |
| MOT expiry date  | 12 April 2024                   |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|                                         |            |
|-----------------------------------------|------------|
| Vehicle class                           | 49         |
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-03-28 |
| Current registration |            |
| Plate since          | 2019-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2004-01-16               |
| Last registration          | 2023-04-13               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2004-01-16 | 10 mi      |
| Registration #2  | 2006-09-12 | 29.788 mi  |
| Registration #3  | 2007-09-11 | 34.303 mi  |
| Registration #4  | 2009-09-30 | 38.648 mi  |
| Registration #5  | 2010-09-29 | 45.749 mi  |
| Registration #6  | 2010-09-29 | 45.749 mi  |
| Registration #7  | 2011-09-30 | 53.729 mi  |
| Registration #8  | 2012-09-29 | 62.172 mi  |
| Registration #9  | 2013-09-29 | 70.217 mi  |
| Registration #10 | 2014-09-29 | 78.262 mi  |
| Registration #11 | 2015-09-29 | 86.307 mi  |
| Registration #12 | 2016-09-29 | 94.352 mi  |
| Registration #13 | 2017-09-29 | 102.397 mi |
| Registration #14 | 2018-09-29 | 110.442 mi |
| Registration #15 | 2023-04-13 | 118.487 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1665 mm |
| Height              | 1490 mm |
| Length              | 3810 mm |
| Wheel base          | 2455 mm |
| Max. allowed weight | 1600 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 45 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of axles    | 2                |
| Engine number      | D3EA3274682      |