



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI HIGHLINE 4MOTION
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #142023-07-25 08:01

MOT test number144984090571

Result✓ Passed

Next expiry date2024-07-24

- Advice**Offside Rear Leaf spring modified but not seriously weakened CORRODED (5.3.1 (d) (i))
- Advice**Offside Rear Shock absorbers has slight external damage to the casing CORROSION (5.3.2 (b))
- Advice**ADJUSTABLE STEERING COLUMN MECHANISM HAS SOME WEAR/MOVEMENT
- Advice**Nearside DOOR MIRROR GLASS DAMAGED
- Advice**Nearside Rear Leaf spring modified but not seriously weakened CORRODED (5.3.1 (d) (i))
- Advice**Nearside Rear Shock absorbers has slight external damage to the casing CORROSION (5.3.2 (b))
- Advice**STEERING RACK HAS WEAR/MOVEMENT IN MAIN MOUNTINGS
- Advice**CRACK IN LOWER SECTION OF WINDSCREEN

**MOT #13**

2023-07-25 08:01

MOT test number

134339573316

Result**✗ Failed****Pass with rectification** Offside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** ADJUSTABLE STEERING COLUMN MECHANISM HAS SOME WEAR/MOVEMENT**Advice** Nearside DOOR MIRROR GLASS DAMAGED**Advice** Nearside Rear Leaf spring modified but not seriously weakened CORRODED (5.3.1 (d) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing CORROSION (5.3.2 (b))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** STEERING RACK HAS WEAR/MOVEMENT IN MAIN MOUNTINGS**Advice** CRACK IN LOWER SECTION OF WINDSCREEN**Advice** Offside Rear Leaf spring modified but not seriously weakened CORRODED (5.3.1 (d) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing CORROSION (5.3.2 (b))**MOT #12**

2022-06-01 09:30

MOT test number

674359120986

Result**✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 255/55R19 (5.2.3 (e))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Oil leak, but not excessive Axle (8.4.1 (a) (i))

**MOT #11** 2021-05-14 12:24**MOT test number** 801894636416**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #10** 2020-05-29 13:48**MOT test number** 618626751093**Result** ✓ Passed**MOT #9** 2020-05-29 13:48**MOT test number** 612123254754**Result** ✗ Failed**Pass with rectification** Rear Service brake excessively binding (1.2.1 (f))**MOT #8** 2019-07-29 10:40**MOT test number** 541794292908**Result** ✓ Passed**MOT #7** 2019-03-07 09:29**MOT test number** 285534671889**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2018-07-26 15:22**MOT test number** 244811974345**Result** ✓ Passed

**MOT #5** 2017-09-01 07:54**MOT test number** 547976712293**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-08-28 14:41**MOT test number** 724021274164**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Fuel pipe leaking at fuel filter (7.2.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-08-26 15:04**MOT test number** 766824099122**Result** ✓ Passed**MOT #2** 2015-09-17 16:29**MOT test number** 844187798338**Result** ✓ Passed**MOT #1** 2014-12-04 12:43**MOT test number** 507368534324**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 July 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		24 July 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-12-09
Last registration	2023-07-25
Complete history	See info



Registration #1	2011-12-09	15 mi
Registration #2	2014-12-04	32.000 mi
Registration #3	2015-09-17	40.038 mi
Registration #4	2016-08-26	46.963 mi
Registration #5	2017-08-28	54.670 mi
Registration #6	2017-09-01	54.670 mi
Registration #7	2018-07-26	62.365 mi
Registration #8	2019-03-07	66.987 mi
Registration #9	2019-03-07	66.987 mi
Registration #10	2019-03-07	66.987 mi
Registration #11	2019-03-07	66.987 mi
Registration #12	2019-03-07	66.987 mi
Registration #13	2019-03-07	66.987 mi
Registration #14	2019-03-07	66.987 mi
Registration #15	2019-03-07	66.987 mi
Registration #16	2019-03-07	66.987 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	2228 mm
Height	1834 mm
Length	5254 mm
Kerb weight	2106 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	CDC 049834