





report date: 2024-03-29

General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	White
Year of manufacture	2015
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	91 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 1

Date 2021-01-22

Pictures 18

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-29
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #10	2023-10-23 14:13
MOT test number	143254706224
Result	✓ Passed
Next expiry date	2024-10-29

MOT #9		2023-10-23 14:13
MOT test number		924816388801
Result		X Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #8	2022-10-04 12:19
MOT test number	638673012790
Result	✓ Passed
MOT #7	2022-10-03 11:17
MOT test number	691502594515
Result	× Failed
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-10-11 10:18 **MOT** test number 979893615032 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice**

MOT #5 2021-10-06 15:45 **MOT** test number 865107389331 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail

MOT #4	2020-10-07 10:35
MOT test number	911541915398
Result	✓ Passed

CarCheck.co.uk page 4/12



Result

KN65FSZ report date: 2024-03-29

X Failed

MOT #3 2019-10-24 11:46

MOT test number 199001005676

Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #2 2019-10-24 09:34

MOT test number 595202494433

Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #1 2018-10-24 15:43

MOT test number 827982043667

Result ✓ Passed

Advice Both front tyres worn on outer edges

CarCheck.co.uk page 5/12



Tax & MOT check



Days left 278

MOT expiry date 29 October 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history

Owner History	
For how long did the current and previous owner(s) have this RENAULT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

Diato changes	More info >
Plate changes See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-10-30
Last registration	2023-10-23
Complete history	See info



Registration #1	2015-10-30	16 mi
Registration #2	2018-10-24	12.043 mi
Registration #3	2019-10-24	16.015 mi
Registration #4	2019-10-24	16.015 mi
Registration #5	2020-10-07	18.363 mi
Registration #6		11.777 es
Registration #7		11.777 mi
Registration #8		71.777 es
Registration #9		11.777 ms
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1965 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

C010924