



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Blue
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-12
Pictures	53
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-23
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	58
Total items failed	10

**MOT #19** 2023-06-20 11:47**MOT test number** 491702853694**Result** ✓ Passed**Next expiry date** 2024-06-23

- Advice** Nearside Rear Nail in tyre
- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm. (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #18**

2023-06-20 11:47

MOT test number

203400920969

Result**✗ Failed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Minor** Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm. (5.2.3 (e))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2022-06-24 10:10

MOT test number

249426647453

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

MOT #16

2022-06-22 15:41

MOT test number

368159795553

Result

✗ Failed

- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2021-06-10 09:55**MOT test number** 484357714067**Result** ✓ Passed**MOT #14** 2020-09-29 12:14**MOT test number** 390547319410**Result** ✓ Passed**Advice** Nearside Front Exhaust has a minor leak of exhaust gases Pipe before rear box (6.1.2 (a))**Advice** Nearside Non obligatory mirror damaged**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2019-09-19 15:47**MOT test number** 181523622385**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**MOT #12** 2019-09-19 08:47**MOT test number** 783209501805**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Non obligatory mirror damaged**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2018-09-14 14:10**MOT test number** 684358058276**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged

**MOT #10** 2017-09-21 11:15**MOT test number** 996440796455**Result** ✓ Passed**MOT #9** 2016-09-21 11:30**MOT test number** 349495183505**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-10-01 10:36**MOT test number** 866152339010**Result** ✓ Passed**MOT #7** 2015-10-01 10:36**MOT test number** 263439139424**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Rear fog lamp not working (1.3.2b)**MOT #6** 2014-09-27 10:56**MOT test number** 506200474260**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-01-24 12:10**MOT test number** 408034724008**Result** ✓ Passed



MOT #4	2014-01-24 12:10
MOT test number	479454924037
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)

MOT #3	2013-01-29 10:54
MOT test number	589799523065
Result	✓ Passed

MOT #2	2012-03-30 14:45
MOT test number	469200092095
Result	✓ Passed

MOT #1	2012-03-30 14:45
MOT test number	737910192023
Result	✗ Failed
Pass with rectification	Centre Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX09YFS
Plate since	2019-03-28
Current registration	EX09YFS
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-31
Last registration	2023-06-20
Complete history	See info



Registration #1	2009-03-31	6 mi
Registration #2	2012-03-30	29.601 mi
Registration #3	2013-01-29	38.305 mi
Registration #4	2014-01-24	50.768 mi
Registration #5	2014-09-27	60.629 mi
Registration #6	2015-10-01	66.822 mi
Registration #7	2015-10-01	66.822 mi
Registration #8	2016-09-21	70.088 mi
Registration #9	2017-09-21	73.997 mi
Registration #10	2018-09-14	79.069 mi
Registration #11	2019-09-20	85.277 mi
Registration #12	2020-09-20	91.485 mi
Registration #13	2021-09-20	97.693 mi
Registration #14	2022-09-20	103.901 mi
Registration #15	2023-06-20	110.109 mi
Registration #16	2023-06-20	110.109 mi
Registration #17	2023-06-20	110.109 mi
Registration #18	2023-06-20	110.109 mi
Registration #19	2023-06-20	110.109 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K79192