



PEUGEOT

SBIOLWC


report date: 2024-03-29

General information

Make	PEUGEOT
Model	5008
Colour	Blue
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type	Diesel
-----------	--------



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-15
Pictures	2
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2022-12-19 14:57
MOT test number	765888481081
Result	✓ Passed
Next expiry date	2023-12-18
Advice	Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))

MOT #13	2021-12-07 16:23
MOT test number	953218388951
Result	✓ Passed

MOT #12	2021-12-07 12:58
MOT test number	139170381139
Result	✗ Failed
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #11	2020-12-17 16:53
MOT test number	428744410154
Result	✓ Passed

MOT #10	2019-07-13 13:17
MOT test number	343157755862
Result	✓ Passed

MOT #9	2019-07-12 13:19
MOT test number	902135938479
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #8** 2018-06-29 16:16**MOT test number** 700490747404**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pad(s) wearing thin unevenly worn (1.1.13 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2018-06-29 08:03**MOT test number** 131243275864**Result** ✗ Failed

- Advice** Offside Rear Nail in tyre
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin unevenly worn (1.1.13 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #6 2017-06-30 12:53**MOT test number** 508203272603**Result** ✓ Passed**MOT #5** 2016-07-08 16:34**MOT test number** 150568529104**Result** ✓ Passed

**MOT #4** 2016-07-08 09:37**MOT test number** 371257269240**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2015-06-26 10:31**MOT test number** 266127675132**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-07-05 10:50**MOT test number** 855916484127**Result** ✓ Passed**MOT #1** 2013-07-16 14:32**MOT test number** 648147893114**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-21
Last registration	2022-12-19
Complete history	See info



Registration #1	2010-07-21	13 mi
Registration #2	2013-07-16	29.325 mi
Registration #3	2014-07-05	35.128 mi
Registration #4	2015-06-26	40.968 mi
Registration #5	2016-07-08	54.725 mi
Registration #6	2016-07-08	54.725 mi
Registration #7	2017-06-30	65.735 mi
Registration #8	2018-06-29	81.817 mi
Registration #9	2019-06-29	97.899 mi
Registration #10	2020-06-29	113.981 mi
Registration #11	2021-06-29	130.063 mi
Registration #12	2022-06-29	146.145 mi
Registration #13	2023-06-29	162.227 mi
Registration #14	2024-06-29	178.309 mi
Registration #15	2025-06-29	194.391 mi
Registration #16	2026-06-29	210.473 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Additional information

Number of seats	7
Engine number	JBBN3117726