





report date: 2024-03-28

General information

Make	CITROEN
Model	C-CROSSER HDI VTR PLUS
Colour	Grey
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	379 Nm at 2.000 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	191 g/km
CO2 label	J



CarCheck.co.uk page 1/13



FH57VLU

report date: 2024-03-28

Internet history

Entry 1

Date 2022-03-07

Pictures 22

Listing price <u>View report</u>





PLEASE CALL
OUR TRADE
CENTRE ON
07950 744827



source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-18
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	24
Total items failed	3

MOT #16		2023-09-16 10:49
MOT test	number	799200746547
Result		✓ Passed
Next exp	iry date	2024-09-18
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriora	ited (5.3.4 (b) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play slight play (5	.3.4 (a) (i))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deterio	rated (5.3.4 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15		2022-09-09 11:35
MOT test	number	322002439289
Result		✓ Passed
Advice	Offside Front Inner Rack End Slight Play	
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1	14 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a)) (ii))

CarCheck.co.uk page 3/13



MOT #14 2022-09-09 11:35

MOT test number 485636854375

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))

Pass with rectification Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))

Advice Offside Front Inner Rack End Slight Play

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2021-09-15 09:08

MOT test number 446973699267

MOT #12 2020-09-15 12:47

MOT test number 657665002160

Result

Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 4/13



FH57VLU

report date: 2024-03-28

MOT test number
973810014816

Result

Advice
Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice
Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice
Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

MOT test number

Result

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9	2017-09-12 08:48
MOT test number	822289135530
Result	✓ Passed
MOT #8	2016-09-16 15:12
MOT test number	857145116264
Result	✓ Passed

Result	✓ Passed
MOT #7	2016-09-14 08:52
MOT test number	280690588192
Result	X Failed
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	

CarCheck.co.uk page 5/13



MOT #6

MOT #3

MOT test number

FH57VLU

report date: 2024-03-28

2015-09-18 08:09

2012-09-19 10:08

248453862239

MOT test n	umber	537114900028
Result		✓ Passed
Advice	Nearside Front Tie bar/rod has slight play in a pin/bush (2.4.G.2)	
MOT #5		2014-09-17 10:05
MOT test n	umber	206600664255
Result		✓ Passed
MOT #4		2013-09-17 16:03
MOT test n	umber	449950863240
Result		✓ Passed

Result	✓ Passed
MOT #2	2011-09-06 09:25
MOT test number	896129141247

Result ✓ Passed

MOT #1	2010-09-18 12:26
MOT test number	351201060424
Result	✓ Passed

CarCheck.co.uk page 6/13



See MOT history

Tax & MOT check

Tax expired: 25 March 2024



axed

✓ MOT

Expires: 18 September 2024

Tax status

Days left

MOT expiry date

Expired at 25 March 2024

34 days too late

18 September 2024

Tax calculation

Full MOT history

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		EN
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13




FH57VLU

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-07
Last registration	2023-09-16
Complete history	See info



Registration #1	2007-12-07	12 mi
Registration #2	2010-09-18	25.930 mi
Registration #3	2011-09-06	36.923 mi
Registration #4	2012-09-19	46.480 mi
Registration #5	2013-09-17	56.392 mi
Registration #6	2014-09-17	64.185 mi
Registration #7	2015-09-18	74.207 mi
Registration #8	2016-09-14	83.538 mi
Registration #9	2016-09-16	83.551 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 12/13



		_		
luma	ncior	ור א.	MOIO	nt.
	ensior	ואט כו	WEIG	HL

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ554015960

CarCheck.co.uk page 13/13