



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H1 C/C CDTI
Colour	Silver
Year of manufacture	2015
Top speed	80 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-12-10
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-06
MOT pass rate	50 %
MOT passed	6
Failed MOT tests	6
Total advice items	35
Total items failed	3

MOT #12	2023-12-09 09:29
MOT test number	491075384995
Result	✓ Passed
Next expiry date	2025-01-06
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2022-12-10 11:42
MOT test number	113752367151
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2022-01-07 15:20
MOT test number	894444458527
Result	✓ Passed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #9** 2021-12-23 11:14**MOT test number** 945427012550**Result** ✗ Failed**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material both pipes ends, slightly corroded (1.1.11 (c))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #8** 2021-03-26 11:04**MOT test number** 225849206776**Result** ✓ Passed**MOT #7** 2021-03-24 16:03**MOT test number** 101516304179**Result** ✗ Failed**MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Nearside Outline marker lamp not working (4.2.1 (a) (ii))**MAJOR** Driver's door catch insecure Door not closing fully (6.2.3 (c) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2020-08-28 10:01**MOT test number** 281173228769**Result** ✗ Failed**Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2020-07-28 12:00**MOT test number** 792729294807**Result** ✗ Failed**MAJOR** Rear Tyre(s) of different sizes are fitted on the same axle. nearside: 235/65/16C offside: 225/65/16C (5.2.3 (b))**Minor** Trailer electrical socket wiring insulation damaged or deteriorated (4.10 (b) (i))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))**DANGEROUS** Rear Body component likely to become detached wooden beam (6.2.1 (a) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Nail in tyre X 2**MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Body component damaged and likely to cause injury (6.2.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2019-07-16 14:35**MOT test number** 704968385129**Result** ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2019-07-16 12:10**MOT test number** 837137055274**Result** ✗ Failed

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #2 2018-07-12 06:56**MOT test number** 316376663717**Result** ✓ Passed**MOT #1** 2018-07-11 12:29**MOT test number** 624072095865**Result** ✗ Failed

Pass with rectification Nearside Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire fuel filler protective cover insecure (6.1.3 (e))

MAJOR Nearside Position lamp not working central body position (4.2.1 (a))

MAJOR Nearside Rear Position lamp not working body position (4.2.1 (a))

MAJOR Offside Rear Position lamp likely to become detached body position (4.2.1 (c) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 January 2025

Tax status		Valid until 1 September
Days left		125
MOT expiry date		6 January 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-07-29
Last registration	2023-12-09
Complete history	See info



Registration #1	2015-07-29	11 mi
Registration #2	2018-07-11	46.370 mi
Registration #3	2018-07-12	46.370 mi
Registration #4	2019-07-16	57.528 mi
Registration #5	2019-07-16	57.528 mi
Registration #6	2020-07-28	69.751 mi
Registration #7	2020-08-28	69.769 mi
Registration #8	2020-09-29	75.277 mi
Registration #9	2020-10-29	75.277 mi
Registration #10	2020-11-29	75.277 mi
Registration #11	2020-12-29	75.277 mi
Registration #12	2021-01-29	75.277 mi
Registration #13	2021-02-29	75.277 mi
Registration #14	2021-03-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2070 mm
Height	2258 mm
Length	5643 mm
Wheel base	3682 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	M9T -C153514 LWL