



Mercedes-Benz



report date: 2024-03-29

## General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Silver
Year of manufacture	2006
Top speed	139 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.4 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 2


Date	2023-10-01
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-08
Pictures	37
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-03
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	38
Total items failed	10

MOT #20 2023-07-31 10:21

MOT test number 348609881117

Result ✓ Passed

Next expiry date 2024-08-03

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Covers fitted to outer sills and parts of underside not allowing full inspection of some areas
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19 2022-08-01 14:47

MOT test number 785498998304

Result ✓ Passed

- Advice** Covers fitted to outer sills and parts of under side not allowing full inspection of some areas
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #18** 2022-08-01 09:39**MOT test number** 108295942099**Result** ✗ Failed**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Covers fitted to outer sills and parts of under side not allowing full inspection of some areas**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #17** 2021-08-04 08:46**MOT test number** 668364337206**Result** ✓ Passed**MOT #16** 2020-08-11 14:08**MOT test number** 411786996072**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #15** 2019-09-03 12:14**MOT test number** 977730708958**Result** ✓ Passed**MOT #14** 2019-09-02 11:31**MOT test number** 425117420415**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn rear (5.3.4 (a) (i))



<b>MOT #13</b>	2018-09-07 10:09
<b>MOT test number</b>	616900672087
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Front Suspension arm ball joint dust cover severely deteriorated front arm (5.3.4 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #12</b>	2017-09-04 13:56
<b>MOT test number</b>	516046244323
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm has slight play in a ball joint rear (2.4.G.2)
<b>Advice</b>	Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt front (2.4.G.2)
<b>Advice</b>	Exhaust tail has a broken mounting

<b>MOT #11</b>	2017-09-04 13:56
<b>MOT test number</b>	219498028528
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt front (2.4.G.2)
<b>Advice</b>	Exhaust tail has a broken mounting
<b>Pass with rectification</b>	Nearside Rear position lamp(s) not working (1.1.A.3b)
<b>Advice</b>	Nearside Front Suspension arm has slight play in a ball joint rear (2.4.G.2)
<b>Pass with rectification</b>	Offside Stop lamp not working (1.2.1b)

**MOT #10** 2016-05-16 08:14**MOT test number** 733296682628**Result** ✓ Passed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt front (2.4.G.2)**MOT #9** 2015-05-21 14:52**MOT test number** 426791245105**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #8** 2014-05-27 13:57**MOT test number** 526077744107**Result** ✓ Passed**MOT #7** 2014-05-27 13:57**MOT test number** 147137544181**Result** ✗ Failed**Pass with rectification** Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-02-06 15:04**MOT test number** 198847033436**Result** ✓ Passed

**MOT #5** 2013-01-12 11:32**MOT test number** 377862513077**Result** ✗ Failed**Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #4** 2012-01-10 11:43**MOT test number** 426140212053**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2011-01-10 13:04**MOT test number** 835850711046**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-01-10 13:04**MOT test number** 695600511005**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-01-15 13:09**MOT test number** 463075710078**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
3 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	3 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>YE56EPO</b>
Plate since	2019-03-29
Current registration	 <b>YE56EPO</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-12-21
Last registration	2023-07-31
Complete history	<a href="#">See info</a>



Registration #1	2006-12-21	12 mi
Registration #2	2010-01-15	15.827 mi
Registration #3	2011-01-10	21.678 mi
Registration #4	2012-01-10	25.739 mi
Registration #5	2013-01-12	30.834 mi
Registration #6	2013-02-06	30.834 mi
Registration #7	2014-05-27	37.619 mi
Registration #8	2015-05-21	42.550 mi
Registration #9	2016-05-16	47.439 mi
Registration #10	2017-09-04	52.616 mi
Registration #11	2017-09-04	52.616 mi
Registration #12	2019-05-29	55.557 mi
Registration #13	2019-05-29	55.557 mi
Registration #14	2019-05-29	55.557 mi
Registration #15	2019-05-29	55.557 mi
Registration #16	2019-05-29	55.557 mi
Registration #17	2019-05-29	55.557 mi
Registration #18	2019-05-29	55.557 mi
Registration #19	2019-05-29	55.557 mi
Registration #20	2019-05-29	55.557 mi
Registration #21	2019-05-29	55.557 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1665 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030735534