



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 SPORT
Colour	Blue
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-28
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-08-23
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	30
Total items failed	9

MOT #21 2023-08-22 07:29

MOT test number 148061778008

Result ✓ Passed

Next expiry date 2024-08-23

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Nearside Rear All position lamps with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #20 2022-08-18 10:12

MOT test number 328672935467

Result ✓ Passed

**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**Advice** Central Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

**MOT #19**

2022-08-18 10:12

**MOT test number**

414711043609

**Result****✗ Failed****Pass with rectification**

Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice**

Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**Advice**

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**Advice**

Central Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))

**Advice**

Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Advice**

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification**

Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice**

Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**MOT #18**

2021-08-17 11:02

**MOT test number**

563318018838

**Result****✓ Passed****Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

**Minor**

Front Anti-roll bar linkage ball joint dust cover severely deteriorated both (5.3.4 (b) (i))

**Advice**

Engine mounting damaged but not to excess (6.1.8 (a) (i))

**MOT #17**

2020-08-22 14:39

**MOT test number**

778483484951

**Result****✓ Passed****Advice**

Offside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Nearside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16** 2020-08-22 14:39**MOT test number** 816679779482**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**MOT #15** 2019-08-21 15:44**MOT test number** 912206758635**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2018-08-24 12:41**MOT test number** 156308827246**Result** ✓ Passed**MOT #13** 2017-08-15 11:57**MOT test number** 429744537388**Result** ✓ Passed**MOT #12** 2016-08-20 12:03**MOT test number** 839802248958**Result** ✓ Passed

**MOT #11** 2016-08-20 12:03**MOT test number** 539453114696**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #10** 2015-07-01 15:11**MOT test number** 338622785158**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-12-02 11:28**MOT test number** 958366734375**Result** ✓ Passed**MOT #8** 2013-06-12 11:30**MOT test number** 277063363144**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2012-06-14 10:18**MOT test number** 925146162145**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2011-06-15 14:59**MOT test number** 479656861129**Result** ✓ Passed

**MOT #5** 2011-06-15 12:43**MOT test number** 246656561423**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2010-06-15 17:12**MOT test number** 403616460163**Result** ✓ Passed**MOT #3** 2010-06-15 09:24**MOT test number** 654496560115**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #2** 2009-04-02 10:32**MOT test number** 701132999049**Result** ✓ Passed**MOT #1** 2008-09-08 10:03**MOT test number** 314222958239**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
23 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	23 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-09
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2005-09-09	19 mi
Registration #2	2008-09-08	27.245 mi
Registration #3	2009-04-02	29.819 mi
Registration #4	2010-06-15	36.323 mi
Registration #5	2010-06-15	36.325 mi
Registration #6	2011-06-15	43.831 mi
Registration #7	2011-06-15	43.831 mi
Registration #8	2012-06-14	50.607 mi
Registration #9	2013-06-12	56.799 mi
Registration #10	2014-12-02	63.728 mi
Registration #11	2015-07-01	66.388 mi
Registration #12	2016-08-20	73.335 mi
Registration #13	2016-08-20	73.335 mi
Registration #14	2016-08-20	73.335 mi
Registration #15	2016-08-20	73.335 mi
Registration #16	2016-08-20	73.335 mi
Registration #17	2016-08-20	73.335 mi
Registration #18	2016-08-20	73.335 mi
Registration #19	2016-08-20	73.335 mi
Registration #20	2016-08-20	73.335 mi
Registration #21	2016-08-20	73.335 mi
Registration #22	2016-08-20	73.335 mi
Registration #23	2016-08-20	73.335 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1256 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX7F2647868